

Additional Funding Request

NY126	CSS# 17767 WO# 8151 Asset# 7513																							
Description of Repairs	Labor and materials to repair motorized gate to MEP.																							
Diagnosis: Initial Work Order	Motorized gate to MEP has broken bearing assembly on chain drive sprocket. Gate can only open and close manually. Routine request.																							
Diagnostic Fee	<p>\$ 160</p> <p>TW Labor \$80/hr x 2</p>																							
Additional Labor Cost to Perform Repairs	<p>\$ 480.00</p> <p>TW Labor \$80/hr x 6</p>																							
Additional Material Cost to Perform Repairs	<p>\$ 278.67</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 2px;">DODGE-P2BSC100 123806 (MULTIPACK 30 PCS)</td> <td style="padding: 2px; text-align: center;">1</td> <td style="padding: 2px; text-align: right;">\$97.08</td> <td style="padding: 2px;"></td> <td style="padding: 2px; text-align: right;">\$97.08</td> </tr> <tr> <td style="padding: 2px;">SEALMASTER-NP-16 0700180 GEN GOLD SET SCREW</td> <td style="padding: 2px; text-align: center;">1</td> <td style="padding: 2px; text-align: right;">\$128.09</td> <td style="padding: 2px;"></td> <td style="padding: 2px; text-align: right;">\$128.09</td> </tr> <tr> <td style="padding: 2px;">MISC MOUNTED UNITS-UCP205-16 0433</td> <td style="padding: 2px; text-align: center;">1</td> <td style="padding: 2px; text-align: right;">\$36.08</td> <td style="padding: 2px;"></td> <td style="padding: 2px; text-align: right;">\$36.08</td> </tr> <tr> <td style="padding: 2px;">Sales Tax</td> <td style="padding: 2px;"></td> <td style="padding: 2px;"></td> <td style="padding: 2px;"></td> <td style="padding: 2px; text-align: right;">\$17.42</td> </tr> </table>				DODGE-P2BSC100 123806 (MULTIPACK 30 PCS)	1	\$97.08		\$97.08	SEALMASTER-NP-16 0700180 GEN GOLD SET SCREW	1	\$128.09		\$128.09	MISC MOUNTED UNITS-UCP205-16 0433	1	\$36.08		\$36.08	Sales Tax				\$17.42
DODGE-P2BSC100 123806 (MULTIPACK 30 PCS)	1	\$97.08		\$97.08																				
SEALMASTER-NP-16 0700180 GEN GOLD SET SCREW	1	\$128.09		\$128.09																				
MISC MOUNTED UNITS-UCP205-16 0433	1	\$36.08		\$36.08																				
Sales Tax				\$17.42																				
Total Cost of Repair	\$ 918.67																							



WORK ESTIMATE

CSS #:

17767

Work Order #:

8151

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	NY126
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g.,	
E-Mail Address:	adam.colopy@tideh2o.net	Classroom/Room #)	
Assigned Technician(s):	Patrick Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to repair motorized gate to MEP.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
DODGE-P2BSC100 123806 (MULTIPACK 30 PCS)	1	\$97.08		\$97.08
SEALMASTER-NP-16 0700180 GEN GOLD SET SCREW	1	\$128.09		\$128.09
MISC MOUNTED UNITS-UCP205-16 0433	1	\$36.08		\$36.08
Sales Tax				\$17.42
Diagnostic			2	\$160.00
SUB-TOTAL COSTS:	Materials Total	\$278.67	Labor	\$640.00
			TOTAL	\$918.67

Quotation

Service Center Address: APPLIED INDUSTRIAL TECHNOLOGIES 525 ERIE BLVD W SYRACUSE, NY 13204-2422 TEL: 315-472-0900 FAX: 315-472-6210				Quote Create Date (MM-DD-YYYY): 02-27-2019	Sales Rep: MATTHEW WISE Phone: Email:		Page: 1/1
Account Manager:				Quotation Number: 506720277	PO #: Req #: Inquiry #:		
Sold-To Address: TIDEWATER INC. 525 ERIE BLVD W SYRACUSE NY 13204-2422				Ship-To Address: TIDEWATER INC. 525 ERIE BLVD W SYRACUSE NY 13204-2422	Account: C2346		
Payment Terms: COD - CASH BASIS				Customer Contact: Customer Contact Phone:			
Transport Mode and Means: CUSTOMER PICKUP, CUSTOMER PICK UP Terms:							
Item #	Quantity	UOM	Manufacturer Part #	Customer Part #	Est Delivery Date	Unit Price (USD)	Extended Price (USD)
000010	1.000	EA	DODGE-P2BSC100 Description: DODG_P2BSC100 Material Sales Text: 123806 P2B-SC-100 (MULTIPAK 30 PCS)			80.900	80.90
000020	1.000	EA	SEALMASTER-NP-16 1-2 DAYS Description: SLMS_NP-16 Material Sales Text: 700180 / GEN GOLD SET SCREW			106.740	106.74
000030	1.000	EA	MISC MOUNTED UNITS-UCP205-16 Description: MMU_UCP205-16 Material Sales Text: 0433			30.060	30.06
SUBTOTAL (WITHOUT TAX) TAX							217.70 17.42
TOTAL IN WORDS: TWO HUNDRED THIRTY-FIVE DOLLARS AND TWELVE CENTS							TOTAL(USD) 235.12
Special Information: Order Notes:							
PRICES QUOTED ABOVE ARE THOSE IN EFFECT AT THE TIME OF QUOTATION. MANUFACTURER INCREASES MAY APPLY UNLESS SPECIFICALLY STATED ON THE FACE OF THIS QUOTATION. RETURNED PRODUCT IS SUBJECT TO A RESTOCKING CHARGE.				THIS QUOTATION CONTAINS CONFIDENTIAL INFORMATION, MAY NOT BE DISCLOSED TO THIRD PARTIES AND IS SUBJECT TO OUR STANDARD TERMS AND CONDITIONS OF SALE, SHOWN ON THE REVERSE SIDE OF THIS DOCUMENT AND AVAILABLE AT WWW.APPLIED.COM . BUYER'S ACCEPTANCE OF SHIPMENT OR PERFORMANCE AND/OR PAYMENT CONSTITUTES ACCEPTANCE OF APPLIED'S TERMS AND CONDITIONS.			
THIS QUOTE MAY CONTAIN ITEMS THAT ARE SPECIAL ORDER, UNIQUE, OR CUT TO SIZE. THESE ITEMS ARE NON-RETURNABLE AND NON-CANCELABLE. YOUR ORDER IS SPECIFICALLY CONDITIONED ON ACCEPTING THESE TERMS.							

