

Additional Funding Request

DE007	CSS# 19755 WO# 9584 Asset# 1703										
Description of Repairs	Labor and materials to remove and replace the thermistor on the Fijitsu mini-split.										
Diagnosis: Initial Work Order	The two mini-split units in the offices of the shop building are not working properly. One of these offices houses the servers for the shop and I have concerns over heat damaging the servers if they are not repaired (reason for the urgent priority)										
Diagnostic Fee	\$ 160 TW Labor \$80/hr x 2										
Additional Labor Cost to Perform Repairs	\$ 1305 SS Mechanical Labor \$95/hr 9 SS Mechanical Diagnostic \$450										
Additional Material Cost to Perform Repairs	\$45.24 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 60%;">10 in. Adjustable Metal Worm Duct Clamps (2-Pack) Sales tax included</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 20%; text-align: right;">\$45.24</td> <td style="width: 10%; text-align: right;">\$45.24</td> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> </tr> </table>			10 in. Adjustable Metal Worm Duct Clamps (2-Pack) Sales tax included	1	\$45.24	\$45.24				
10 in. Adjustable Metal Worm Duct Clamps (2-Pack) Sales tax included	1	\$45.24	\$45.24								
Total Cost of Repair	\$ 1,510.24										



S&S Mechanical

Location: Fleming-Godwin USARC

344 North New Street

Dover, DE 19904

Proposal Submitted to: Adam Colopy

Project: DE001 WO# 9584

Office # 301-574-1555

Fax # 301-574-1558

seth@sandsmidatlantic.com

sandsmidatlantic.com

S&S proposes to come out and remove and replace the thermistor on the Fijitsu mini-split:

Diagnostic Total: \$450.00

Materials: \$45.24

Thermistor QTY 2 /k9900965013/ \$45.24

Labor: \$855.00

1 HVAC Technician/9 Hours/\$95.00 rate=\$855.00

Full estimated total: \$1,350.24

Payments to be made as follows: 15 days upon approved invoice

Respectfully submitted: Brian Davis/Lindsay Ruby

Dated: 06/28/19



JOHNSTONE SUPPLY THE BALSAN GROUP

JOHNSTONE ANNAPOLIS
1981 MORELAND PKWY, SUITE 101
ANNAPOLIS, MD 21401
Phone 410-280-0101
Fax 410-280-0104

SOLD TO:

S&S MECHANICAL
4845 SOUTH CRAIN HIGHWAY
UPPER MARLBORO, MD 20772

Acknowledgement

ORDER DATE	ORDER NUMBER
06/28/2019	100-100694476
JOHNSTONE ANNAPOLIS 1981 MORELAND PKWY, SUITE 101 ANNAPOLIS, MD 21401 Phone 410-280-0101 Fax 410-280-0104	
PAGE NO. 1 of 1	

SHIP TO:

S&S MECHANICAL
4845 SOUTH CRAIN HIGHWAY
UPPER MARLBORO, MD 20772

CUSTOMER NUMBER	CUSTOMER PO NUMBER	JOB NAME / RELEASE NUMBER	SALESPERSON		
14831	thermistor				
WRITER		SHIP VIA	TERMS	SHIP DATE	FREIGHT ALLOWED
Shawn Eller - 44 Anna		PICK UP	Cash on Delivery	06/28/2019	No
ORDER QTY	DESCRIPTION			UNIT PRICE	EXT PRICE
1ea	G36-597 K9900965013 THERMISTOR Pn: 158970			17.780/ea	17.78
				Subtotal	17.78
				S&H Charges	0.00
				Tax	1.07
				Amount Due	18.85

CAUTION

- R410A refrigerant is charged in this Air-Conditioner.
- By additional charging, do not mix other refrigerant.
- Connecting the pipes, vacuuming and additional charging shall be done correctly as instructed in the installation manual.

MOVING PARTS

**CAUTION: MOVING PARTS.
DO NOT OPERATE UNIT WITH
CABINET REMOVED.**

DO NOT REMOVE CABINET REMOVED.
WARNING: RISK OF ELECTRIC SHOCK.
CAN CAUSE INJURY OR DEATH.
DISCONNECT ALL REMOTE ELECTRIC
POWER SUPPLIES BEFORE SERVICING.

AVERTISSEMENT: RISQUE DE CHOC
ELECTRIQUES. PEUT CAUSER DES
BLESSURES ET MEME ENTRAINER
LA MORT. COUPER LES SOURCES
D'ALIMENTATION A DISTANCE
AVANT LE DEPANNAGE.

Audi **CERTIFIED**
www.audiusa.com

SPLIT TYPE AIR CONDITIONER
OUTDOOR USE
MODEL No. AQU18RLXFZ
SERIAL No. LTN 021536
220V 60Hz 1-PH

SOURCE 208/230 V 60Hz 1-PH		COOL	HEAT
TOTAL	AMPS	10.0/10.0	10.0/10.0
COMPRESSOR AMPS	8.5/8.5	8.5/8.5	8.5/8.5
OUTDOOR FAN MOTOR AMPS	0.5/0.5	0.5/0.5	0.5/0.5
CAPACITY		12.1 A	15 A



OUTDOOR CONDENSER	FAN MOTOR	AMPS	12.1	A
MINIMUM CIRCUIT AMPACITY			15	A
MAX. CKT. BKR.			24	A
COMPRESSOR LOCKED-ROTOR AMPERES			4.8	14 oz
REFRIGERANT R410A FACTORY CHARGED			240	psi
DESIGN PRESSURE HIGH SIDE			240	psi
DESIGN PRESSURE LOW SIDE				

APPLICABLE INDOOR UNIT	ASU12RLF	ASUM1F1
ASU7RLF	ASU7RLF1	
ASU12RLF2	ASU12RLF	AGU12RLF
ASUM1F2	ASU9RLF	AGU9RLF
AU77RLF	ATU12RLF	
ATU7RLF		

Hisicon NFI Compatible

MADE IN THAILAND

FLUITSU GENERAL LIMITED

FUJITSU GENERAL LIMITED

