

Additional Funding Request

MD002	CSS# 19942 WO# 8845 Asset# 1808			
Description of Repairs	Labor and materials to replace tow actuator valves on asset #1808			
Diagnosis: Initial Work Order	While performing PM found two actuator valves that needed replaced.			
Diagnostic Fee	\$0			
Additional Labor Cost to Perform Repairs	\$ 640.00 TW Labor \$80/hr x 8			
Additional Material Cost to Perform Repairs	\$ 1,286.20			
	Dca, Sr Stem Down, 3/4in. Stroke 135lb Model # ML745A3013	1	\$598.23	\$1,196.46
	Sales Tax			\$89.74
CM Credit	\$-250.00			
Total Cost of Repair	\$ 1,676.20			



WORK ESTIMATE

CSS #: 19942

Work Order #: 8845

Emergency ☐ Urgent ☐

Routine ☐ CM ☐

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace two actuator valves on Asset #1808.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Dca, Sr Stem Down, 3/4in. Stroke 135lb Model # ML745A3013	2	\$598.23		\$1,196.46
Sales Tax				\$89.74
SUB-TOTAL COSTS:		Materials Total	\$1,286.20	Labor \$640.00
TOTAL			\$1,926.20	

All Products

33P987

Search

HVAC and Refrigeration > HVAC Controls and Thermostats > Pneumatic Controls > Pneumatic Damper Actuators >
Dca, Sr Stem Down, 3/4In. Stroke, 135 Lb >

Print

Email

HONEYWELL

Dca, Sr Stem Down, 3/4In. Stroke, 135 Lb

Item # 33P987 Mfr. Model # ML7425A3013 Catalog Page # N/A UNSPSC # 31251504

No
Image
Needed

Web Price ⓘ

\$498.52 / each



One Time Delivery

1

Add to Cart

+ Add to List



Shipping



Pickup

Expected to arrive **Thu, May 30**

Ship To 43065 (Change)

Jump to:



Replacement Parts



Be the first to write a review



Shipping Weight 5.8 lbs.

How can we improve our Product Images?

☐ CompareCountry of Origin **Hungary** | Country of Origin is subject to change.


Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order.
More




Honeywell

ML7425B3012

24V 60Hz 12VA Class 2
0 or 2 to 10VDC Selectable
135 LBF 3/4" Stroke 1.5min
BR - Reverse Acting



1877 TEMP IND & REG EQ
MNH6AP/CLIS MN55422




Honeywell GmbH
D-71101 Sindelfingen
Made in Hungary

N314 1130

<http://europe.hbt.honeywell.com>







WARRANTY INFORMATION
WARRANTY PERIOD: 1 YEAR
WARRANTY COVERAGE: LABOR AND MATERIALS
WARRANTY EXCLUSIONS: MISUSE, ACCIDENT, AND NEGLIGENCE
WARRANTY CLAIMS: CONTACT YOUR DEALER OR THE MANUFACTURER
WARRANTY CONTACT: 1-800-555-1234

CAUTION!
READ MANUAL AFTER
REPAIRING BEFORE
RESTARTING THE UNIT

Cer
SHM-1