

## Additional Funding Request

<b>MD002</b>	<b>CSS# 20763 WO# 11244 Asset# 1116</b>								
Description of Repairs	Labor and materials to install new unloader solenoid and check valve. Provide new electronic drain valve and strainer assembly. Verify proper operation.								
Diagnosis: Initial Work Order	Additional work needed on air compressor								
Diagnostic Fee	\$0								
Additional Labor Cost to Perform Repairs	\$815 TW Labor 3 hours @ \$ 80/hr Cummings Wagner \$575								
Additional Material Cost to Perform Repairs	\$768 <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 5px;"> <tr> <td style="width: 50%;">See attached Detail</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 20%; text-align: right;">\$768.00</td> <td style="width: 10%;"></td> <td style="width: 10%; text-align: right;">\$768.00</td> </tr> </table>				See attached Detail	1	\$768.00		\$768.00
See attached Detail	1	\$768.00		\$768.00					
Total Cost of Repair	\$1,583								



*"A 100% Employee Owned Company"*

10901 Pump House Road  
Annapolis Junction, MD 20701-1125  
Balt.(410) 792-4230 • Wash.(301) 953-9370  
Fax: (301) 490-7156

---

---

**Mechanical Equipment  
Sales & Service**

---

---

November 15, 2019

**Tidewater Inc.  
CSS  
700 E. Ordinance Rd.  
Baltimore, MD**

**Attn: Tina Lee**

**Re: Gardner Denver Compressor Repair**

Provide labor and material to repair customer's Gardner Denver model Apex 5-15 s/n D100921 air compressor located at the above mentioned site.

**SCOPE OF WORK**

Secure equipment per OSHA  
Provide and install new unloader solenoid and check valve  
Provide new electronic drain valve and strainer assembly for customer installation  
Start machine check operation and adjusted as needed  
Report problems to customer

**Parts - \$768.00  
Labor - \$575.00  
Total - \$1,343.00**

**Proposal covers mentioned work only, other work found to be necessary to be performed only after customer approval**

**Work to be performed during normal business hours**

**Tax and shipping for parts not included if applicable will be added during invoicing.**

**Pricing good for 30 days from proposal date and is subject to the attached terms and conditions**

**RESPECTFULLY SUBMITTED:  
CUMMINS-WAGNER CO., INC.  
Brian Brooks  
Assistant Service Manager**

CSS-TIDEWATER GD REPAIR 11-19.DOC

[www.cummins-wagner.com](http://www.cummins-wagner.com)

Ashland, VA • Virginia Beach, VA • Annapolis Junction, MD • Warrenton, VA • Winchester, VA • Elizabethtown, PA • Williamsport, PA  
(804) 550-3311 (800) 550-3373 (301) 490-9007 (540) 341-7794 (540) 868-1829 (717) 367-8294 (717) 321-1188

Job #:

Customer PO#:

Date: 10/18/19

PO #:

EXT. PO#

Customer:

TIDEWATER (CSS)

Contact:

Cindy / Tim Lee

Address:

700 E. ORDINANCE Rd  
BALTO, MD 21246

Phone:

210-531.0225 / 614-623-9565

Email:

MFG:

GID

Model:

APEX-15A

S/N:

D100921

Size:

Quan	Disp	Description	Part#	Cost	Sell	Ext
1		Unloader Solenoid	91B248			400.39
1		Airb drain	PD7020			198.00
1		Steamer Assy	BV200 1/4			69.00
1		Check Valve	90AR261			100.74
						768.13
		4 hrs Labor				
		4x 13.25 = 52.00		571.70		575.00
		19x 2x 6.15 = 43.70				1343.13
						\$1343.00



