

Additional Funding Request

MD003	CSS# 20887 WO# 10608 Asset# NA												
Description of Repairs	Labor and materials needed to replace toilet and urinal in men's 1 st floor bathroom.												
Diagnosis: Initial Work Order	There is a leaking toilet and a leaking urinal in the 1st floor men's room. Both have cracks in them. See attached pictures.												
Diagnostic Fee	\$ 160 TW Labor \$80/hr x 2												
Additional Labor Cost to Perform Repairs	\$ 640 TW Labor \$80/hr x 8												
Additional Cost	\$ 716.92 <table border="1" style="margin-left: 20px;"> <tr> <td>Toilet Bowl #16T992</td> <td>1</td> <td>\$253.66</td> <td>\$253.66</td> </tr> <tr> <td>Urinal #16U006</td> <td>1</td> <td>\$426.42</td> <td>\$426.42</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td>\$36.84</td> </tr> </table>	Toilet Bowl #16T992	1	\$253.66	\$253.66	Urinal #16U006	1	\$426.42	\$426.42	Sales Tax			\$36.84
Toilet Bowl #16T992	1	\$253.66	\$253.66										
Urinal #16U006	1	\$426.42	\$426.42										
Sales Tax			\$36.84										
Total Cost of Repair	\$ 1,516.92												



WORK ESTIMATE

CSS #: Work Order #:
Emergency Urgent Routine X

Company Name:	Tidewater, Inc.	Facility ID:	MD003
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g.,	
E-Mail Address:	adam.colopy@tideh2o.net	Classroom/Room #)	
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT			
Labor and materials to replace toilet and urinal in men's 1st floor bathroom.			

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Toilet Bowl #16T992	1	\$253.66		\$253.66
Urinal #16U006	1	\$426.42		\$426.42
Sales Tax				\$36.84
Diagnostic			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$716.92	Labor \$800.00
			TOTAL	\$1,516.92

[Home](#) > [Shared Cart](#)

2 Products in tina's Shared Cart

The product(s) selection below has been provided to you for your shopping convenience from a Shared Cart so that you may easily add item(s) to your cart for purchase.

 Select All[Add to Cart](#)

Item	Price	Qty	Total Price
<input type="checkbox"/>  Toilet Bowl, Mounting Style Floor, Bowl Shape Elongated, Gallons per Flush 1.28, Water Surface Area 9 in. x 8 in., Bowl Height 16-1/2 in., Bowl Width 14 in., Bowl Depth 30-1/4 in., For Use With Tank Type Gravity Fed Tank, Collection Champion(R) PRO(TM) Right Height(TM), For Use With Mfr. Model Number 4225A104.020, 4225A154.020, 4225A164.020, 4225A174.020, 4225A105.020, Bolt to Seat Front 18-7/16 in., Rim Height 16-1/2 in., Trapway Dia. 2-3/8 in., Rough-In 12 in. Item #: 16T992	Web Price \$211.38 / each	<input type="text" value="1"/>	\$211.38
<input type="checkbox"/>  Urinal, Washout, Wall Mounting Style, Connection (In.) 3/4, Material of Construction Vitreous China, Color/Finish White, Height (In.) 26-1/8, Width (In.) 18-7/8, Depth (In.) 14-1/8, 0.125 to 1.0 Gallons per Flush, Cartridges Required No, Standards ASME A112.19.2-2008/CSA B45.1-08, ANSI A117.1, Includes Spud, (2) Wall Hangers, Strainer, and Outlet Connection Item #: 16U006	Web Price \$355.35 / each	<input type="text" value="1"/>	\$355.35

Total Price \$566.73 Select All[Add to Cart](#)[Chat with an Agent](#)



