

Additional Funding Request

NY051	CSS# 21705 WO# 5091 Asset# 10069				
Description of Repairs	Labor and materials replace chain and broken brackets on gate.				
Diagnosis: Initial Work Order	Drive chain and adjustment bolt needs to be replaced along with the adjustment bolt				
Diagnostic Fee	\$160 TW Labor 2 hours @ \$ 80/hr				
Additional Labor Cost to Perform Repairs	\$640 TW Labor 8 hours @ \$ 80/hr				
Additional Material Cost to Perform Repairs	\$362.56				
	100' #40 Chain	1	\$234.30		\$234.30
	Chain Bolts	2	\$11.40		\$22.80
	Chain Bracket	1	\$82.80		\$82.80
	Tax	1	\$22.66		\$22.66
Total Cost of Repair	\$1,162.56				



WORK ESTIMATE

CSS #: 21705

Work Order #: 5091

Emergency ☐

Urgent ☒

Routine ☐

Company Name:	Tidewater, Inc.	Facility ID:	NY051
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Gate
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Patrick Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials replace chain and broken brackets on gate.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
100' #40 Chain	1	\$234.30		\$234.30
Chain Bolts	2	\$11.40		\$22.80
Chain Bracket	1	\$82.80		\$82.80
Tax	1	\$22.66		\$22.66
Diagnostic Labor			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$362.56	Labor \$800.00
TOTAL			\$1,162.56	



