

Additional Funding Request

NY113	CSS# 2815 WO# 6914 Asset# NA							
Description of Repairs	Labor and materials needed to replace the card reader.							
Diagnosis: Initial Work Order	GATE NOT WORKING AMSA SHOP ENTRANCE urgent							
Diagnostic Fee	\$160 TWI Labor \$ 80/hr x 2							
Additional Labor Cost to Perform Repairs	\$ 300 Labor \$ 75/hr x 4							
Additional Cost	\$ 198 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">HID iClass Reader</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 20%; text-align: right;">\$198.00</td> <td style="width: 30%; text-align: right;">\$198.00</td> </tr> </table>				HID iClass Reader	1	\$198.00	\$198.00
HID iClass Reader	1	\$198.00	\$198.00					
Total Cost of Repair	\$ 658.00							

LoCurrent Systems, LLC

3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 1497**DATE** 01/27/2020**P.O. NUMBER**

Mattydale, NY Replace Reader

	ACTIVITY	QTY	AMOUNT
01/27/2020	Services CSS# 21815 WO# 6914 Mattydale, NY USARC NY113 AMSA Shop Entrance Gate Replace (1) Reader	1	498.00

Dear Ms. Lee:

As per your request, LoCurrent Systems is pleased to provide a quotation to replace (1) nonfunctional Reader at the Mattydale, NY USARC NY113 AMSA Shop Entrance Gate..

Cost Breakdown:

(1) HID iClass Reader.....	\$198.00
(1) Man 4 hours @ \$75.....	\$300.00

Grand Total.....	\$498.00
------------------	----------

The cost for the above mentioned is \$498.00.

If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.

Thank you for thinking of LoCurrent Systems.

Sincerely,

ACTIVITY	QTY	AMOUNT
Antonietta LoRusso		
	TOTAL	\$498.00

Accepted By

Accepted Date