

## Additional Funding Request

<b>VA006</b>	<b>CSS# 21904 WO# 11236 Asset# NA</b>
Description of Repairs	Labor to perform PM of 2 boilers at VA006
Diagnosis: Initial Work Order	PM Boilers 1 and 2 prior to startup
Diagnostic Fee	\$0
Additional Labor Cost to Perform Repairs	\$ 640 TW Labor \$80/hr x 8
Additional Material Cost to Perform Repairs	\$0
Total Cost of Repair	\$ 640



# WORK ESTIMATE

CSS #:	21904	Work Order #:	11236		
Emergency	<input type="checkbox"/>	Urgent	<input type="checkbox"/>	Routine	<input checked="" type="checkbox"/> X
Company Name:	Tidewater, Inc.		Facility ID:	VA006	
Contractor POC:	Adam Colopy				
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	Boiler Room	
E-Mail Address:	<a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a>				
Assigned Technician(s):	Bill Davis				

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT					
Labor to perform PM of 2 boilers at VA006					

LABOR/MATERIAL			MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY				
Labor				8	\$640.00
SUB-TOTAL COSTS:		Materials Total	\$0.00	Labor	\$640.00
		TOTAL	\$640.00		