

Region: 5

Location: VA099

CSS #: 21944

Maximo Work Order No.: 11246

Asset #: NA

Date Issued: 10/22/19

Original Description:

Short or fault in outside building lighting. The breaker for the outside building lighting keeps tripping due to a fault and or issue with a ballast. find the short and repair so that the lighting is operating properly. This includes the lighting for the Flag

Repairs Needed:

Moore's is proposing to return to site. Will remove and replace four wall packs on site. Once the new wall packs are installed, will test and ensure proper operation. Per vendor, there are no replacement parts available for these particular style/brand of lights. Complete wall pack replacement is the only option in order to keep all wall pack lighting the same on site. Customer is responsible for any and all restocking charges that apply should the quote be cancelled after Moore's has received approval

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Materials (See attached Detail)	--	--	\$6,887.39	--	\$6,887.39
--	NA	Moore's Labor	12.5	120	--	--	\$1,500.00
--	NA	TW Coordination and Oversite	4	80	--	--	\$320.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
16.5	\$1,820.00	\$6,887.39	\$0.00	\$8,707.39	100%	\$8,707.39



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

Proposal

December 4, 2019

Quotes are valid for 30 days.

USARC - VA #099 Bedford
1117 Harmony Lane
Bedford VA 24523
Email

tina.lee@tideh2o.net

Contact Name Tina Lee & Adam Colopy
Telephone N/A
Cell Phone 614-623-9569
CSS/WO 21944/ 11246

DESCRIPTION OF EQUIPMENT:

Wall Pack replacements

DESCRIPTION OF PROBLEM:

Moore's electrician on site found the wall pack that was causing the breaker to trip. Electrician removed that fixture. There is also another wall pack that is out and should be replaced. Found two wall packs that are flashing and the manufacturer of these particular wall packs does not offer parts replacement. If customer would like to have the same style wall packs, then will need to replace all four wallpacks in question.

DESCRIPTION OF REPAIRS:

Moore's is proposing to return to site. Will remove and replace four wall packs on site. Once the new wall packs are installed, will test and ensure proper operation. Per vendor, there are no replacement parts available for these particular style/brand of lights. Complete wall pack replacement is the only option in order to keep all wall pack lighting the same on site.

Customer is responsible for any and all restocking charges that apply should the quote be cancelled after Moore's has received approval

MATERIAL, EQUIP OR PARTS

	Quantity	Sell price
Wall Pack	4.00	\$ 6,488.50
Material Tax	1.00	\$ 343.89
Truck Fee	1.00	\$ 55.00
Material Total	\$	6,887.39

LABOR ITEMIZED

		Labor
Labor - Incurred	3.5	\$ 120.00 \$ 420.00
Labor - One Man	9	\$ 120.00 \$ 1,080.00
Labor Total		\$ 1,500.00

Thank you for your business. If you have any questions or concerns, please feel free to contact us via telephone or quotes@mooreselectric.com

Materials **\$ 6,887.39**
Labor **\$ 1,500.00**
TOTAL **\$ 8,387.39**

*This does not include
original call cost.*

Robert Lowery, Changeout Estimator 434-309-2591
Amy Hockaday, Estimator 434-309-2569
James Davis, Estimator 434-309-2568
Adam Barker, Estimator 434-369-3514
Jared Underwood, Estimator 434-306-2446

Approved by: _____

Standard Terms and Conditions

Payments past 30 days are subject to 1.5% monthly service charge on unpaid balance. Additional charges for payments made through credit cards may apply. Late payments sent to collections or legal process the purchaser agrees to pay all costs, expenses, and reasonable attorney fees.

CONSOLIDATED ELECTRICAL DIST.

125 BRADLEY DRIVE

LYNCHBURG VA 24501

TEL: 434 616-6547 FAX: 434 616-6548

CONTACT: STUART EARLEY

QUOTE FOR: MOORES ELECTRICAL & MECHANICAL

ACCT #: UM-58000 MOORES ELECTRICAL & MECHANIC

PO BOX 119
ALTAVISTA, VA 24517

QUOTATION		PAGE 001 OF 001	
QUOTE #	DATE	REV #	REV DATE
1012908	12/02/19	001	12/02/19
QUOTE EXPIRES		PREPARED BY	
01/01/2020		SE	
SLS		INSL	
7395		0007	
FOB		FREIGHT	
		SHIPPING POINT	PREPAID

CUS PO #:
US ARMY RESERVE
JOB NAME:

LN	QTY	MFR	CATALOG #	DESCRIPTION	PRICE	UOM	EXT AMT
01	4	CPL	ENVF02LED120BL4BKCWB	INVUE WALL LIGHT	1,351.77	E	5,407.08

TOTAL: 5,407.08

PLEASE NOTE: THIS IS NOT AN OFFER TO CONTRACT, BUT MERELY A QUOTATION OF CURRENT PRICES FOR YOUR CONVENIENCE AND INFORMATION. ORDERS BASED ON THIS QUOTATION ARE SUBJECT TO YOUR ACCEPTANCE OF THE TERMS AND CONDITIONS LOCATED AT SALES.OUR-TERMS.COM, WHICH WE MAY CHANGE FROM TIME TO TIME WITHOUT PRIOR NOTICE. WE MAKE NO REPRESENTATION WITH RESPECT TO COMPLIANCE WITH JOB SPECIFICATIONS.

Tran-Bal

GP250CKT9TMXH

P/N 4 0000065



0313
10.8V 2500mAh

NICKEL-CADMIUM BATTERY

MUST BE RECYCLED OR

DISPOSED OF PROPERLY

(888-263-4638)



WARNING

NEVER DISCONNECT BATTERY
UNLESS AC POWER AND
THE CONVERTER CONNECTOR
ARE DISCONNECTED



AC
DISCONNECTED

WARNING

NEVER DISCONNECT BATTERY
UNLESS AC POWER AND
THE CONVERTER CONNECTOR
ARE DISCONNECTED

WARNING

Tran-Bal
GP250CKT9TMXH
P/N 4 0000065
10.8V 2500mAh
NICKEL-CADMIUM BATTERY



5212
Ni-Cd
10.8V 2500mAh
NICKEL-CADMIUM BATTERY
MUST BE RECYCLED OR
DISPOSED OF PROPERLY.

MADE IN CHINA

MADE IN CHINA

5212
Ni-Cd
10.8V 2500mAh
NICKEL-CADMIUM BATTERY
MUST BE RECYCLED OR
DISPOSED OF PROPERLY.

MADE IN CHINA

MADE IN CHINA



