

Additional Funding Request

VA050	CSS# 21965 WO# 11239 Asset# NA
Description of Repairs	Labor to perform PM and Annual certification of a boiler at VA050.
Diagnosis: Initial Work Order	PM and certify boiler (1) that weren't on the inventory per Rick. This can be done by the PM contract.
Diagnostic Fee	\$0
Additional Labor Cost to Perform Repairs	\$ 658.35 TW Labor \$80/hr x 6 Argent – \$178.35
Additional Material Cost to Perform Repairs	\$0
Total Cost of Repair	\$ 658.35



WORK ESTIMATE

CSS #: Work Order #:
Emergency Urgent Routine

Company Name:	Tidewater, Inc.	Facility ID:	VA050
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Boiler Room
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Bill Davis		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor to perform PM and Annual certification of a boiler at VA050.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
SUB-TOTAL COSTS:	Materials Total	\$0.00	Labor	\$480.00
TOTAL			\$480.00	

Argent Inspections, Inc.

QUOTATION—TIDEWATER, INC. 55TH USARC REGION 5, ZONE 3 VA050 USARC RICHMOND BOILER INSPECTIONS

Date: 10/15/2019

Quotation #: 0225-191015-03

Customer ID: 0225

Ship To:

Tidewater, Inc.
Attn: Adam Colopy, FMP
3761 Attucks Drive
Powell, OH 43065

Respond To:

Argent Inspections, Inc.
133 Haywick Ct.
Charleston, SC 29414

Quantity	Item	Units	Description	Unit Price	Total
1	Inspection	Job	Inspection of 1 boiler at USARC Charlottesville in addition to contracted inventory, preparation and submission of paperwork.	\$ 178.35	\$ 178.35
Notice: Lack of preparation or discovery of mechanical or electrical problems could require more time than scheduled for inspection, which may result in additional charges.				Total	\$ 178.35

Phone: 843-763-3549
Fax: 843-408-4463
Cell: 843-817-6701
E-mail: geoff@argentinsp.com

Argent Inspections is a National Board Authorized Inspection Agency, and all inspections are performed by Commissioned In-Service Inspectors in accordance with the National Board Inspection Code, The ASME Boiler and Pressure Vessel Code, and the applicable Jurisdictional Requirements. Additionally, all inspectors are licensed to perform inspections by the State of South Carolina and have their credentials on file with NAVFAC