

Additional Funding Request

NY051	CSS# 22124 WO# 6483 Asset# NA			
Description of Repairs	Labor and Materials to replace stained ceiling tiles throughout the facility.			
Diagnosis: Initial Work Order	INSTALL NEW CEILING TILES MAIN HALL Way and AFOS OFFICE			
Diagnostic Fee	\$160			
Additional Labor Cost to Perform Repairs	\$640 TW Labor 8 hours @ \$ 80			
Additional Material Cost to Perform Repairs	\$498.25			
	Ceiling Tiles, Armstrong Pack of 16 - 5NGJ8 (includes sales tax)	5	\$99.65	\$498.25
Total Cost of Repair	\$1,298.25			



WORK ESTIMATE

CSS #: 22124

Work Order #: 6483

Emergency ☐

Urgent ☐

Routine ☒

Company Name:	Tidewater, Inc.	Facility ID:	NY051
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Various
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Patrick Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and Materials to replace stained ceiling tiles throughout the facility.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Ceiling Tiles, Armstrong Pack of 16 - 5NGJ8 (includes sales tax)	5	\$99.65		\$498.25
Diagnostic Labor			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$498.25	Labor \$800.00
TOTAL			\$1,298.25	



Cart

Item Item Availability	Quantity	Total Price
---------------------------	----------	-------------



ARMSTRONG Ceiling Tile, Width 24",
Length 24", 5/8" Thickness, Mineral
Fiber, PK 16
Item #5NGJ8
Your Price: **\$77.37**

5

\$386.85

Expected to arrive **Tue.**
Dec 17 using standard
ground shipping
(additional shipping
options available at
Checkout.)







VAV 11



EXIT