

Additional Funding Request

VA050	CSS# 22160 WO# 11267 Asset# NA									
Description of Repairs	Labor and material to fix ceiling tile grid and replace the ceiling tiles									
Diagnosis: Initial Work Order	Room 317 the ceiling tiles and grids are damaged and need to be replaced approximately six each grids and tiles. Three light fixtures out in male latrine on first floor.									
Diagnostic Fee	<p>\$240</p> <p>TW Labor 3 hours @ \$ 80/hr</p>									
Additional Labor Cost to Perform Repairs	<p>\$1280</p> <p>TW Labor 16 hours @ \$ 80/hr</p>									
Additional Material Cost to Perform Repairs	<p>\$97.04</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 2px;">Ceiling Tiles (Box of 16)</td> <td style="padding: 2px;">2</td> <td style="padding: 2px;">\$48.52</td> <td style="padding: 2px;"> </td> <td style="padding: 2px;">\$97.04</td> </tr> </table>					Ceiling Tiles (Box of 16)	2	\$48.52		\$97.04
Ceiling Tiles (Box of 16)	2	\$48.52		\$97.04						
Total Cost of Repair	\$1,617.04									



WORK ESTIMATE

CSS #:

22160

Work Order #:

11267

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	VA050
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	RM 317
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Bill Davis/ Richard Walker		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and material to fix ceiling tile grid and replace the ceiling tiles

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			16	\$1,280.00
Ceiling Tiles (Box of 16)	2	\$48.52		\$97.04
Diagnostic Labor			3	\$240.00
SUB-TOTAL COSTS:		Materials Total	\$97.04	Labor \$1,520.00
			TOTAL	\$1,617.04



All Departments

Home Decor & Furniture

DIY Projects & Ideas

Installation & Services

Specials & Offers



Local Ad

Home / Building Materials / Ceilings / Ceiling Tiles / Drop Ceiling Tiles

Internet #203628467 Model # R2110 Store SKU #563139



PERFORMANCE FEATURES



USG Ceilings

2 ft. x 2 ft. Radar Lay-In Ceiling Panel (16-Pack)

(93) [Write a Review](#) [Questions & Answers \(31\)](#)

- Quick and easy installation
- Aids in sound absorption
- Easily maintained with a soft brush or vacuum

Covers 64 sq. ft.

60¢ /sq. ft. **\$38.51** /case

Save up to \$100[®] on your qualifying purchase.
[Apply for a Home Depot Consumer Card](#)

How much flooring will you need?

Sq. Ft. (Width x Length)

Enter Square Footage

Calculate

+ Add Room

Share

Save to Favorites

Print



