

Additional Funding Request

VA006	CSS# 22353 WO# 11273 Asset# NA														
Description of Repairs	Labor and materials to repair 5 flush valves on toilets.														
Diagnosis: Initial Work Order	Shut water down and check all toilet flush valves for gravel and or debris in flush assemble														
Diagnostic Fee	<p>\$160</p> <p>TW Labor 2 hours @ \$ 80/hr</p>														
Additional Labor Cost to Perform Repairs	<p>\$640</p> <p>TW Labor 8 hours @ \$ 80/hr</p>														
Additional Material Cost to Perform Repairs	<p>\$159.08</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Sloan Rebuild Kit 5P213</td> <td style="width: 10%; text-align: center;">5</td> <td style="width: 10%; text-align: center;">\$30.30</td> <td style="width: 10%;"></td> <td style="width: 10%; text-align: center;">\$151.50</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td></td> <td style="text-align: center;">\$7.58</td> </tr> </table>					Sloan Rebuild Kit 5P213	5	\$30.30		\$151.50	Sales Tax				\$7.58
Sloan Rebuild Kit 5P213	5	\$30.30		\$151.50											
Sales Tax				\$7.58											
Total Cost of Repair	\$959.08														



WORK ESTIMATE

CSS #:

22353

Work Order #:

11273

Emergency

Urgent

X

Routine

Company Name:	Tidewater, Inc.	Facility ID:	VA006
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Restrooms
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Bill Davis		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to repair 5 flush valves on toilets.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Sloan Rebuild Kit 5P213	5	\$30.30		\$151.50
Sales Tax				\$7.58
Diagnostic Labor			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$159.08	Labor \$800.00
			TOTAL	\$959.08

SLOAN

Rubber, Flushometer Rebuilding Kit, Regal Flush Valves, 3.5 gpf For Use With

Item # 5P213 Mfr. Model # A38A Catalog Page # 2747 UNSPSC # 40141636



Web Price 1
\$25.25 / each



One Time Delivery

Add to Cart[+ Add to List](#)

Shipping



Pickup

Expected to arrive Thu. Nov 07.

Ship To 43065 (Change)


Jump to:

 **Replacement Parts**

Shipping Weight 0.3 lbs.

Country of Origin USA | *Country of Origin is subject to change.*

Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order.
[More](#)



SLOAN

Water Connects US®

5P213

5P213

Sloan Kit No. A-38-A
3.5 gpf (13.2 Lpf)

**Water Closet
Flushometer Repair Kit**

Recommended for use with Water Saver closets installed prior to 1997

Can also be used with most blow out style water closets and some older blow out style urinals.