

Additional Funding Request

VA050	CSS# 22780 WO# 11292 Asset# NA														
Description of Repairs	<p>Labor and materials to replace blower motor on boiler #1.</p> <p>Note: Munchkin boilers are no longer manufactured, and it is becoming harder and harder to locate parts. Based on the age and current condition of these boilers we recommend replacing both boilers with new in the near future.</p>														
Diagnosis: Initial Work Order	Boiler # 1 would not light for operational. Need to repair boiler and make sure its operational to get re-certified.														
Diagnostic Fee	\$320														
Additional Labor Cost to Perform Repairs	<p>\$640</p> <p>TW Labor 8 hours @ \$ 80</p>														
Additional Material Cost to Perform Repairs	<p>\$623.58</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Munchkin Blower Motor - 7350P-159 (includes tax)</td> <td style="width: 10%;">1</td> <td style="width: 10%;">\$608.58</td> <td style="width: 10%;"></td> <td style="width: 10%;">\$608.58</td> </tr> <tr> <td>Shipping</td> <td>1</td> <td>\$15.00</td> <td></td> <td>\$15.00</td> </tr> </table>					Munchkin Blower Motor - 7350P-159 (includes tax)	1	\$608.58		\$608.58	Shipping	1	\$15.00		\$15.00
Munchkin Blower Motor - 7350P-159 (includes tax)	1	\$608.58		\$608.58											
Shipping	1	\$15.00		\$15.00											
Total Cost of Repair	\$1583.58														



WORK ESTIMATE

CSS #: 22780

Work Order #: 11292

Emergency

Urgent

Routine

X

Company Name:	Tidewater, Inc.		Facility ID:	VA050
Contractor POC:	Adam Colopy			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net			
Assigned Technician(s):	Richard Walker			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT


Labor and materials to replace blower motor on boiler #1.

Note: Munchkin boilers are no longer manufactured and it is becoming harder and harder to locate parts. Based on the age and current condition of these boilers we recommend replacing both boilers with new in the near future.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Munchkin Blower Motor - 7350P-159 (includes tax)	1	\$608.58		\$608.58
Shipping	1	\$15.00		\$15.00
Diagnostic Labor			4	\$320.00
SUB-TOTAL COSTS:		Materials Total	\$623.58	Labor \$960.00
		TOTAL	\$1,583.58	

P) > Munchkin & Elite Parts

Part 7350P-159: Blower Motor



This is a regular stock item, and will generally ship out the same day or next business day (depending on the time of day the order is received.) If item is out of stock we will notify you of the estimated delivery time.

This part is used with the following models and versions:

Munchkin R1 (11/01/02 - 12/19/06): [399M](#)

Munchkin R2 (after 12/20/06): [399M](#), [399 VWH](#)

MODCON: [300](#), [300VWH](#), [500](#), [500VWH](#), [1000](#), [1000VWH](#)

Elite: [EL-220](#), [EL-299](#), [EL-399](#)

Elite VWH Volume Water Heater: [EL-220 VWH](#), [EL-299 VWH](#), [EL-399 VWH](#)

Elite Premier: [EP-220](#), [EP-299](#), [EP-399](#)

Elite EFT: [EFT-199](#), [EFT-285](#), [EFT-399](#)

Place Order Securely:

(Personal information is entered on our secured server at time of checkout.)

Munchkin Blower Motor (with Gasket

7500P-075)

7350P-159

\$483.00

[Add to Cart](#)



AA

romancart.com



	Price	Total
	\$483.00	\$483.00
Subtotal		\$483.00
Shipping		\$15.00
Ex		\$0.00
Total		\$498.00

[Checkout](#)

es require their residents to self-report usage

Hawaii

g charges for orders within the Continental
any additional shipping charges prior to
strongly encouraged to get a custom shipping
(boilers, water heaters, etc.) that require



