

Additional Funding Request

VA050	CSS# 24240 WO# 11954 Asset# NA
Description of Repairs	As per your request, LoCurrent Systems is pleased to provide a quotation to diagnose and repair/replace the nonfunctional Security Monitor in Room 211 at the Richmond, VA AFRC VA050.
Diagnosis: Initial Work Order	Security monitor in room 211 is not working
Diagnostic Fee	\$0
Additional Labor Cost to Perform Repairs	\$600.00 (1) Man 8 Hours @ \$75.....\$600.00
Additional Material Cost to Perform Repairs	\$580.00 (1) 24" Northern Monitor.....\$450.00 (1) Ethernet to Media Converter.....\$130.00
Total Cost of Repair	\$1,180.00

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 1528
DATE 03/16/2020

P.O. NUMBER

Richmond, VA USARC Monitor

	ACTIVITY	QTY	AMOUNT
03/16/2020	Services CSS#24240 WO# 11954 Richmond, VA AFRC VA050	1	1,180.00

Dear Mr. Colopy:

As per your request, LoCurrent Systems is pleased to provide a quotation to diagnose and repair/replace the nonfunctional Security Monitor in Room 211 at the Richmond, VA AFRC VA050.

Cost Breakdown:

(1) 24" Northern Monitor.....\$450.00
(1) Ethernet to Media Converter.....\$130.00
(1) Man 8 Hours @ \$75.....\$600.00

Grand Total.....\$1,180.00

The cost for the above mentioned is not to exceed \$1,180.00.

If acceptable, please do not hesitate to contact us so we may schedule for work to be completed.

Thank you for thinking of LoCurrent

ACTIVITY	QTY	AMOUNT
Systems.		
Sincerely,		
	TOTAL	\$1,180.00

Accepted By

Accepted Date