

Additional Funding Request

NY067	CSS# 23252 WO# 6901 Asset# NA									
Description of Repairs	Labor and Materials to replace motor on OMS Unit heater.									
Diagnosis: Initial Work Order	Unit heater in OMS shop will not run. Appears that motor has seized. Mike Moseman cell 518-421-2252									
Diagnostic Fee	\$320									
Additional Labor Cost to Perform Repairs	<p>\$640 TW Labor 8 hours @ \$ 80</p>									
Additional Material Cost to Perform Repairs	<p>\$461.05</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Modine Motor - 9F0300950000</td> <td>1</td> <td>\$461.05</td> <td></td> <td>\$461.05</td> </tr> </table>					Modine Motor - 9F0300950000	1	\$461.05		\$461.05
Modine Motor - 9F0300950000	1	\$461.05		\$461.05						
Total Cost of Repair	\$1,421.05									



WORK ESTIMATE

CSS #: 23252

Work Order #: 6901

Emergency

X

Urgent

Routine

Company Name:	Tidewater, Inc.		Facility ID:	NY067
Contractor POC:	Adam Colopy			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	Various
E-Mail Address:	adam.colopy@tideh2o.net			
Assigned Technician(s):	Patrick Brown			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and Materials to replace motor on OMS Unit heater.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Modine Motor - 9F0300950000	1	\$461.05		\$461.05
Diagnostic Labor			4	\$320.00
SUB-TOTAL COSTS:		Materials Total	\$461.05	Labor \$960.00
		TOTAL	\$1,421.05	

Ship To:

TIDEWATER INC
6625 SELNICK DR #A
ELKRIDGE, MD 21075-6220
US
Shipper Account:

Information

Grainger Quote Number 2043005885
Print Date 01/02/2020
Customer Account 885295220
Department Number
Contact Name PATRICK BROWN
Contact Phone 3156723272
Contact Fax
Contact Email patrick.brown@tideh20.net
Requested by Brittany
Garza
Requestor Phone No.
Requestor Fax
Requestor Email Brittany.Garza@grainger.com

eQuote Information:

Quote 2043005885 has been delivered to Grainger websites and Patrick Brown has been notified via email that the quote is available for on-line purchasing.

Comments: Prior authorization is required for ALL returns; product must be new/unused and in original packaging. All returns may be subject to a restocking fee, assessed by the supplier upon inspection. Customer is responsible for return-shipping costs.

Line	Description	MFG Part No	Lead Time Bus.days	Qty.	Unit	Quote Price	Extended Price
------	-------------	-------------	--------------------	------	------	-------------	----------------

10		9F0300950000	3	1	EA	357.96	357.96
----	--	--------------	---	---	----	--------	--------

MODINE MOTOR TO HEATER

Mfr Brand Name MODINE

Customer Part No.:

Carrier: 29811 - UPS GROUND

Cost expiration date: 02/01/2020

Taxable: YES

Estimated Freight	8.37
Total Sell Price in USD	366.33

This is not an invoice. Changes to product or quantities may result in different pricing. Availability and lead times are subject to change and can be confirmed at order placement. Additional lead time may apply for AK and HI. Unless otherwise stated, these items are sold for domestic consumption in the United States. If exported, purchaser assumes full responsibility for compliance with U. S. export control. Contact Sales Rep. or Grainger branch listed below for questions, order placement or to submit a new request. **Return Policy: Please contact Grainger before returning any product. All returns are subject to the manufacturer's return policy. Special Order items may not be returnable. Restocking fees may apply.**

Thank You!

Call or visit us at

Grainger, Inc.

827 Fisher Dr.

Waterloo, IA 50701-9371

D617K