

Additional Funding Request

MD024	CSS# 23351 WO# 13826 Asset# NA							
Description of Repairs	S&S proposes to remove and replace existing wooden door frame, aluminum threshold, once installed, door and frame will be painted to protect. A commercial lock will be furnished and installed. Dispose of removed door.							
Diagnosis: Initial Work Order	Replace wooden door frame of tool room with metal frame in bldg. 1003.							
Diagnostic Fee	<p>\$ 160</p> <p>Labor \$160/hr x 1</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 960</p> <p>Labor \$80/hr x 12</p>							
Additional Material Cost to Perform Repairs	<p>\$ 840.14</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Parts</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 20%; text-align: center;">840.14</td> <td style="width: 30%; text-align: center;">840.14</td> </tr> </table>				Parts	1	840.14	840.14
Parts	1	840.14	840.14					
Total Cost of Repair	\$ 1960.14							



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 548

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 13626
Quote No: 548
Site: MD024 Ordnance Road
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 03/12/2021
Valid For: 30 Day(s)

WO#: 13826

CSS Ticket Number: 23351

Problem: Replace wooden door frame of tool room with metal frame in building 1003.

S&S proposes to remove and replace existing wooden door with steel door, frame, aluminum threshold; once installed, door and frame will be painted to protect. A commercial lock will be furnished and installed. Dispose of removed door.

Service

Item	Quantity	Unit Price	Total
1 3FS DW-16-4 558 3068 CRS KD LH			
1 MFP Welded Closer Reinf			
1 HMD H18-4 CRS F 3068 (CYL			
1 Lockset AL53PD SAT 11-096 10-025 626	1.00	\$760.14	\$760.14
1 Gasketing 160 V 1 X 36" + 2 X 84" US28			
1 Door Sweep 102 VA X 36" US28			
1 Handicap Threshold 513 X 36" AL			
Shipping	1.00	\$80.00	\$80.00
Diagnosis Fee	1	\$160.00	\$160.00
General Maintenance Labor Rate	12	\$80.00	\$960.00
		Sub-Total ex Tax	\$1,960.14
		Tax	\$0.00
		Total inc Tax	\$1,960.14

Labor	\$1,120.00
Materials	\$840.14
Sub-Total ex Tax	\$1,960.14
Tax	\$0.00
Total inc Tax	\$1,960.14

AMERICAN DOOR CO

5016 COOK RD, BELTSVILLE, MD, 20705 Tel: 301-937-9510 FAX: 301-937-0074

QUOTATION

REVIEW THIS QUOTE CAREFULLY, AS WE WILL
FURNISH ONLY THOSE ITEMS INCLUDED HEREIN

Quotation No : 145082
Date : 12 MAR 2021
Account : 50
Page No. : 1

Customer:
CASH ACCOUNT
DEPOSIT REQUIRED ON ALL
ORDERS BEFORE PROCESSING

Ship to:
S & S MECHANICAL
LINDSAY RUBY 301-574-1555
customer pick up

Salesperson : 10 Freight : Terms : Cash Only
Ship Via : CUSTOMER PICK UP

Qty	Description	Unit Price	Extension
1	3FS DW-16-4 558 3068 CRS KD LH		
1	MFP Welded Closer Reinf		
1	HMD H18-4 CRS F 3068 (CYL)		
1	Lockset AL53PD SAT 11-096 10-025 626		
1	Gasketing 160 V 1 X 36" + 2 X 84" US28		
1	Door Sweep 102 VA X 36" US28		
1	Handicap Threshold 513 X 36" AL		
	revised 3-12		
	Product Sub-total	633.45	
	MARYLAND @6.000%	38.01	
	<hr/> Total	671.46	

The above prices are quoted subject to acceptance within 30 days and credit approval by an officer of our company. State and local taxes are not included unless specifically noted. Material will be billed proportionately as shipped. Full amount of invoice due when rendered--retainage not acceptable. On shipments made by common carrier consigned to the customer, all claims for damages in transit must be filed by consignee. We do not include cost of unloading, storage or protection of material at jobsite.



