

## Additional Funding Request

<b>VA049</b>	<b>CSS# 23680 WO# 11961 Asset# NA</b>
Description of Repairs	LoCurrent Systems is pleased to provide a quotation to replace the Main Entrance Card Reader and Weather Shield at the Dervishian Facility (VA049) in Richmond, VA and test for proper functionality.
Diagnosis: Initial Work Order	Need to have CAC reader replace because the current one is not working . POC is Mr. Mark Ander
Diagnostic Fee	\$0
Additional Labor Cost to Perform Repairs	\$300.00 Labor: 1 man 4 hour..... 300.00
Additional Material Cost to Perform Repairs	\$1460 (1) Veridt Stealth Multi-mode Reader (\$200 core rebate if card reader is intact..... \$1250.00 (1) Weather Shield..... 210.00
Total Cost of Repair	\$1,760

**LoCurrent Systems, LLC**

3522 County Highway 11  
 Cooperstown, NY 13326  
 (607)293-7300  
 locurrent@gmail.com



# Estimate

**ADDRESS**

Tidewater Inc.  
 6625- A Selnick Drive  
 Elkridge, MD 21075

**ESTIMATE #** 1503**DATE** 03/16/2020**P.O. NUMBER**

Dervishian VA049 Reader and WS

**SALES REP**

A. LoRusso

	ACTIVITY	QTY	AMOUNT
03/16/2020	<b>Installation Service</b> CSS# 23680 WO# 11961 Dervishian, VA VA049 Re: Card Reader and Weather Shield Replacement	1	1,760.00

Dear Ms. Lee:

LoCurrent Systems is pleased to provide a quotation to replace the Main Entrance Card Reader and Weather Shield at the Dervishian Facility (VA049) in Richmond, VA and test for proper functionality. The cost to repair is as follows:

(1) Veridt Stealth Multi-mode Reader	
(\$200 core rebate if card reader is intact.....	
\$1250.00	
(1) Weather	
Shield.....	210.00
Labor: 1 man 4	
hour.....	300.00
Price is based on performing work while in	
Richmond, VA on other service.	
Total.....	
\$1760.00	

If acceptable, please feel free to contact us so that we may schedule service to be completed.

Thank you for thinking of LoCurrent Systems.

Sincerely,

ACTIVITY	QTY	AMOUNT
Antonietta LoRusso		
	<b>TOTAL</b>	<b>\$1,760.00</b>

Accepted By

Accepted Date