

Additional Funding Request

MD002	CSS# 11771 WO# 11731 Asset# NA			
Description of Repairs	Labor and materials to replace failed Cypher lock.			
Diagnosis: Initial Work Order	Replace failed lockset with secure lever set, rm 106, bldg 0314. 6x keys to match style/type as bldg 002			
Diagnostic Fee	\$ 160 Labor \$80/hr x2			
Additional Labor Cost to Perform Repairs	\$ 320 Labor \$80/hr x 4			
Additional Cost	\$ 417.89			
	Lock M# 7KC 37 AB 14D S3 626 w/TAX	1	\$409.03	\$409.03
	Keys	6	8.86	53.16
Total Cost of Repair	\$ 897.89			



WORK ESTIMATE

CSS #: 23761

Work Order #: 11771

Emergency ☐ Urgent ☐

Routine ☒

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	Rm 106 bldg 0314
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace faile cypher lock rm 106 bldg 0314. 6x keys to match style.type as bldg 002

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			4	\$320.00
Lock w/tax (See detail attached)	1	\$409.03		\$409.03
Keys	6	\$8.86		\$53.16
Diagnostic			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$417.89	Labor
			TOTAL	\$897.89

[Back](#)

Details



BEST

Lever, Mechanical, Heavy Duty,
Keyed Alike, Satin Chrome, 2-3/4"
Backset, Cylindrical

Item # **45CK35**Mfr Model # **7KC 37 AB 14D S3 626**

ZOOM



Qty

1

Your Price

\$323.34

/ each

ADD TO CART**ADD TO LIST****AVAILABILITY**

Home



Cart



Account



Branches



More

