

Additional Funding Request

CSS# should be CSS 23823 rather than 23826

DE007	CSS# 23826 WO# 12175 Asset# NA						
Description of Repairs	Boiler #1 had a bad pressure switch and would ne a PM Kit. After installation SS will check the system to ensure everything is working properly.						
Diagnosis: Initial Work Order	Need PM kit for NO 1 boiler pressure switch bad. Will send additional quote						
Diagnostic Fee	\$ 0.00 Labor \$80/hr x 0						
Additional Labor Cost to Perform Repairs	\$ 1,200 Labor \$100/hr x 12						
Additional Cost	\$ 382.64						
	<table><tr><td>PM Kit/4-50-SP0401 W/tax & shipping</td><td>1</td><td>\$382.64</td><td>\$382.64</td></tr></table>				PM Kit/4-50-SP0401 W/tax & shipping	1	\$382.64
PM Kit/4-50-SP0401 W/tax & shipping	1	\$382.64	\$382.64				
Total Cost of Repair	\$ 1,582.64						



S&S MECHANICAL

S&S Mechanical
4845 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 240

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 12175
Quote No: 240
Site: DE007 Olgetown Road
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 05/04/2020
Valid For: 30 Day(s)

WO#: 12175
CSS Ticket Number: 23826
Problem: PM Kit needed

S&S diagnosed Boiler No 1 had a bad pressure switch and would need a PM kit. After installation, S&S will then check the system to ensure everything is working properly.

Service

Item	Quantity	Unit Price	Total
PM Kit/ 4-50-SP0401	1.00	\$316.80	\$316.80
Tax	1.00	\$15.84	\$15.84
Shipping	1.00	\$50.00	\$50.00
HVAC Labor Rate	12	\$100.00	\$1,200.00
Sub-Total ex Tax			\$1,582.64
Tax			\$0.00
Total inc Tax			\$1,582.64

Labor	\$1,200.00
Materials	\$382.64
Sub-Total ex Tax	\$1,582.64
Tax	\$0.00
Total inc Tax	\$1,582.64

