

Additional Funding Request

DE002	CSS# 23830 WO# 11564 Asset# 190918-124									
Description of Repairs	Labor and materials to replace bad motor in FCU.									
Diagnosis: Initial Work Order	There was a bad motor that was identified during while the PM tech was performing the monthly PM. This is in reference to Maximo WO 11564 POC is Mr. Castellanos at 302-727-2042 Associated Asset ID number:									
Diagnostic Fee	\$0									
Additional Labor Cost to Perform Repairs	\$640 TW Labor 8 hours @ \$ 80									
Additional Material Cost to Perform Repairs	\$129.78 <table border="1"><tr><td>Motor 4MA19</td><td>1</td><td>\$129.78</td><td></td><td>\$129.78</td></tr></table>					Motor 4MA19	1	\$129.78		\$129.78
Motor 4MA19	1	\$129.78		\$129.78						
PM Credit	(\$250.00)									
Total Cost of Repair	\$519.78									



WORK ESTIMATE

CSS #: 23830

Work Order #: 11564

Emergency ☐

Urgent ☐

Routine ☒

Company Name:	Tidewater, Inc.	Facility ID:	DE002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace bad motor in FCU.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Motor 4MA19	1	\$129.78		\$129.78
Diagnostic Labor				\$0.00
SUB-TOTAL COSTS:		Materials Total	\$129.78	Labor \$640.00
TOTAL			\$769.78	

All Products

4MA19

Search

Bulk Order Pad

Cart (1)

Product Categories / [Motors](#) / [HVAC Motors](#) / [Room Air Conditioner Motors](#) / 1/10 HP Room Air Conditioner Motor,Shaded Pole,...

Print

Email

CENTURY

1/10 HP Room Air Conditioner Motor,Shaded Pole,1050 Nameplate RPM,115 Voltage,Frame 42Y

Item # **4MA19** Mfr. Model # **89** Catalog Page # **45** UNSPSC # **26101611**



Web Price

\$103.00 / each

1

Add to Cart

+ Add to List |

Confirm ZIP Code to determine availability.

43065

Save

Shipping Weight **10.1 lbs.**

Country of Origin Mexico | *Country of Origin is subject to change.*



Save money on this similar product!



DAYTON 1/10 HP Room Air Conditioner Motor,Permanent Split...
 Web Price
\$86.00 / each

View Specs

Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order. [More](#)



How can we improve our [Product Images?](#)

Compare

UNIVERSAL ELECTRIC CO.
SER 11SA 18760K MOD. DA3D157N#
115V 60HZ 1.45A 1050RPM SP23
OIL ONCE PER YEAR WITH #20 NON-DET OIL
THERMALLY PROTECTED ROTATION

Fan coil #1



DE002 Building 1
Asset# 190918-124 fan coil Heater

