

Additional Funding Request

VA050	CSS#24240 WO# 11954 Asset# NA							
Description of Repairs	Replace non-functional DVR and perform as well all necessary Programming, Testing, Camera, refocusing and cleaning							
Diagnosis: Initial Work Order	Security monitor in room 211 is not working							
Diagnostic Fee	\$ 450							
Additional Labor Cost to Perform Repairs	\$ 1250 Labor \$75/hr x 16 Admin Fee \$50							
Additional Material Cost to Perform Repairs	\$ 716.04 <table border="1"><tr><td>Hanwha Wisenet DVR</td><td>1</td><td>716.04</td><td>716.04</td></tr></table>				Hanwha Wisenet DVR	1	716.04	716.04
Hanwha Wisenet DVR	1	716.04	716.04					
Total Cost of Repair	\$ 2,416.04							

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 1687

DATE 10/29/2020

P.O. NUMBER

Richmond AFRC VA050 Replace DVR

	ACTIVITY	QTY		AMOUNT
10/29/2020	Services Follow Up Quotation as per Estimate #1528 (CSS#24240 WO#11954): Richmond AFRC VA050 Replace DVR & refocus/clean Cameras	1	1,966.04	1,966.04

Dear Ms. Lee:

LoCurrent Systems is pleased to provide a Follow Up Quotation to replace the nonfunctional DVR at the Richmond, VA AFRC VA050 found to be nonfunctional while on site diagnosing issues being experienced with the Security Monitor; Estimate #1528, CSS#24240, WO#11954 as well as perform all necessary Programming Testing, Camera refocusing & cleaning.

Cost Breakdown:

(1) new Hanwha Wisenet
DVR.....\$716.04
(2) men 8 hours @
\$75.00.....\$1,200.00
Administrative.....\$50.00

Grand
Total.....\$1,966.04

The cost to replace DVR with new, program, test, refocus & clean cameras is \$1,966.04.

If acceptable, please do not hesitate to contact us so we may get DVR on order.

ACTIVITY	QTY	AMOUNT
----------	-----	--------

Thank you.

Sincerely,

Antonietta LoRusso

TOTAL	\$1,966.04
-------	------------

Accepted By	Accepted Date
-------------	---------------

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID: VA050Date of Visit: 10-28-20

Building: _____

CSS: 24240

Contractor Personnel on Site:

~~CMMS~~ 60-11954 Quote 15281. Keith PearsonService Order: ☒2. Chris DeNikrCorrective Maintenance: ☐

Service Order Work Performed:

Unit: CAMERA SManufacturer: Ten-Vison

Model: _____

Serial: _____

Description: Upon arrival at site Found that the
DVR was dead. Building had been struck
By lightning. will need to send quote
for replacement of DVR

Repairs: _____

To be signed by the Contractor:

Print Name: Keith PearsonDate: 10-28-20Signed: [Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed.

Print Name/Rank: CPT Thessolonia FriendDate: 28 OCT 20Signed: [Signature]E-Mail: thessolonia.m.friend.mil@med.mil



EverFocus®





