

## Additional Funding Request

<b>NY051</b>	<b>CSS# 24610 WO# 15193</b>							
Description of Repairs	Tidewater proposes labor and materials to replace the Co2 sensor in AHU1 and reprogram.							
Diagnosis: Initial Work Order	AHU1 CO2 space sensor reading -470 degrees. Troubleshoot and repair sensor.							
Diagnostic Fee	<p>\$ 160</p> <p>Labor \$80/hr x 2</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 640</p> <p>Labor \$80/hr x 8</p>							
Additional Material Cost to Perform Repairs	<p>\$ 313.15</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Carbon Dioxide Transmitter</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 10%; text-align: center;">313.15</td> <td style="width: 10%; text-align: center;">313.15</td> </tr> </table>				Carbon Dioxide Transmitter	1	313.15	313.15
Carbon Dioxide Transmitter	1	313.15	313.15					
Total Cost of Repair	\$ 1,113.15							



# WORK ESTIMATE

CSS #:

24610

Work Order #:

15193

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	NY051
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	<a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a>		
Assigned Technician(s):	Patrick Brown		

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace the Co2 sensor in AHU1 and reprogram.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Carbon Dioxide Transmitter	1	\$313.15		\$313.15
Labor			8	\$640.00
<b>SUB-TOTAL COSTS:</b>		<b>Materials Total</b>	<b>\$313.15</b>	<b>Labor</b>
		<b>TOTAL</b>		<b>\$800.00</b>
				<b>\$1,113.15</b>

**Ship To:**

TIDEWATER INC  
3409 COLD SPRINGS RD  
BALDWINSVILLE, NY 13027-9405  
US  
Shipper Account:

**Information**

Grainger Quote Number 2049255193  
Print Date 11/05/2021  
Customer Account 885295220  
Department Number  
Contact Name PATRICK BROWN  
Contact Phone 3156723272  
Contact Fax  
Contact Email patrick.brown@tideh2o.net  
Customer PO  
Customer Job Name

**eQuote Information:****Comments:**

Line	Description	MFG Part No	Lead Time Bus.days	Qty.	Unit	Quote Price	Extended Price
10	CARBON DIOXIDE TRANSMITTER	CDT-2D40	3	1	EA	239.76	239.76
	Mfr Brand Name DWYER INSTRUMENTS						
	Customer Part No.:						
	Carrier: 22327 - FDX GROUND						
	Cost expiration date: 12/05/2021						
	Taxable: YES						
					Estimated Freight	8.77	
					Total Sell Price in USD		248.53

This is not an invoice. Changes to product or quantities may result in different pricing. Availability and lead times are subject to change and can be confirmed at order placement. Additional lead time may apply for AK and HI. Unless otherwise stated, these items are sold for domestic consumption in the United States. If exported, purchaser assumes full responsibility for compliance with U. S. export control. Contact Sales Rep. or Grainger branch listed below for questions, order placement or to submit a new request. RETURN POLICY: Sourced Product is subject to the manufacturer's return policy and may not be returnable. Please contact Grainger at Customer Care at 1-800-GRAINGER (472-4643) to verify whether your Sourced Product item(s) can be returned. A restocking fee and other charges may apply. Returned Sourced Product must be in new/unused and in original packaging. Customer is responsible for return shipping costs for Sourced Products. No cancellations, refunds or credits are allowed for items marked in Sourced Product quotations or invoices as "Non-Cancellable" or "Non-Returnable".

**Thank You!**

**WW GRAINGER INC**  
**827 FISHER DR**  
**WATERLOO IA 50701-9371**

**Dwyer®**

Dwyer Instruments, Inc.  
Michigan City, IN 46360 U.S.A.  
[www.dwyer-inst.com](http://www.dwyer-inst.com)

MADE IN USA OF U.S. & IMPORTED PARTS

P/N **101636-70**


MDL **CDT-2D40**

S/N **0351FK**

ORD **IP33508**

D/C **M16AF**

**CE**



440745-20 R3

Dwyer.  
Series 401