

ATTACHMENT J-6200000-05
FORMS

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID: VA048

Building: Matheth

Contractor Personnel on Site:

1. Keith Pearson
2. Peter H.

Date of Visit: 4-22-20

CSS: 24834

CMMS: WO 12168

Service Order: ☒

Corrective Maintenance: ☐

Service Order Work Performed:

Unit: Door module

Manufacturer: Galaxy

Model: DRM

Serial: _____

Description: Diagnosed defective DRM module Causing
No operation of the Gate Reader and the
Drill Hall Door.
Also found Ants in the Gate operator

Repairs: Replaced DRM programmed, & tested with staff.
Unseamed Ants sealed All penetrations installed traps
All Normal functionality returned.

To be signed by the Contractor:

Print Name: Keith Pearson Date: 4-22-20

Signed: [Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Kim D Date: 22 APR 20

Signed: KC [Signature]

E-Mail: _____



VEHICLE DETECTOR

VEHICLE DETECTOR

SHADOW
RESET

WIEGAND

RS232

STATUS

VERSION 1.0

S/N 12345678

Smart Touch

DUAL GATE

COM A B

Q09

Q10

Q11

Q12

Q13

Q14

Q15

Q16

Q17

Q18

Q19

Q20

Q21

Q22

Q23

Q24

Q25

Q26

Q27

Q28

Q29

Q30

Q31

Q32

Q33

Q34

Q35

Q36

Q37

Q38

Q39

Q40

Q41

Q42

Q43

Q44

Q45

Q46

Q47

Q48

Q49

Q50

Q51

Q52

Q53

Q54

Q55

Q56

Q57

Q58

Q59

Q60

Q61

Q62

Q63

Q64

Q65

Q66

Q67

Q68

Q69

Q70

Q71

Q72

Q73

Q74

Q75

Q76

Q77

Q78

Q79

Q80

Q81

Q82

Q83

Q84

Q85

Q86

Q87

Q88

Q89

Q90

Q91

Q92

Q93

Q94

Q95

Q96

Q97

Q98

Q99

Q100

Q101

Q102

Q103

Q104

Q105

Q106

Q107

Q108

Q109

Q110

Q111

Q112

Q113

Q114

Q115

Q116

Q117

Q118

Q119

Q120

Q121

Q122

Q123

Q124

Q125

Q126

Q127

Q128

Q129

Q130

Q131

Q132

Q133

Q134

Q135

Q136

Q137

Q138

Q139

Q140

Q141

Q142

Q143

Q144

Q145

Q146

Q147

Q148

Q149

Q150

Q151

Q152

Q153

Q154

Q155

Q156

Q157

Q158

Q159

Q160

Q161

Q162

Q163

Q164

Q165

Q166

Q167

Q168

Q169

Q170

Q171

Q172

Q173

Q174

Q175

Q176

Q177

Q178

Q179

Q180

Q181

Q182

Q183

Q184

Q185

Q186

Q187

Q188

Q189

Q190

Q191

Q192

Q193

Q194

Q195

Q196

Q197

Q198

Q199

Q200

Q201

Q202

Q203

Q204

Q205

Q206

Q207

Q208

Q209

Q210

Q211

Q212

Q213

Q214

Q215

Q216

Q217

Q218

Q219

Q220

Q221

Q222

Q223

Q224

Q225

Q226

Q227

Q228

Q229

Q230

Q231

Q232

Q233

Q234

Q235

Q236

Q237

Q238

Q239

Q240

Q241

Q242

Q243

Q244

Q245

Q246

Q247

Q248

Q249

Q250

Q251

Q252

Q253

Q254

Q255

Q256

Q257

Q258

Q259

Q260

Q261

Q262

Q263

Q264

Q265

Q266

Q267

Q268

Q269

Q270

Q271

Q272

Q273

Q274

Q275

Q276

Q277

Q278

Q279

Q280

Q281

Q282

Q283

Q284

Q285

Q286

Q287

Q288

Q289

Q290

Q291

Q292

Q293

Q294

Q295

Q296

Q297

Q298

Q299

Q300

Q301

Q302

Q303

Q304

Q305

Q306

Q307

Q308

Q309

Q310

Q311

Q312

Q313



LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



INVOICE

BILL TO

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

INVOICE # 1630
DATE 04/23/2020
DUE DATE 05/23/2020
TERMS Net 30

P.O. NUMBER

Montieth VA048 Access Control

DESCRIPTION	QTY	RATE	AMOUNT
Installation EMERGENCY CALL: No Corresponding Estimate CSS# 24834 Montieth Facility Richmond, VA VA048 Access Control Service	1	1,746.00	1,746.00

LoCurrent Systems arrived on site, found that Galaxy DRM Board needed replacing;
replaced Board in Galaxy Cabinet, Flashed Board and Tested.
Also made mechanical adjustments to Gate and raised Gate to prevent rubbing on curb.
Tested all Readers for proper operation.

Cost Breakdown:

(1) DRM Board.....\$546.00
(2) men 8 hours @ \$75.....\$1,200.00

Grand Total.....\$1,746.00

The cost for the above mentioned work is \$1,746.00.

Thank you for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

If you have any questions regarding this invoice, please contact Antonietta
LoRusso at (607)293-7300.

BALANCE DUE

\$1,746.00