

Additional Funding Request

NY127	CSS# 25072 WO# 8692 Asset# NA
Description of Repairs	Labor and materials to replace motor on return fan (RE-1-T) and fuses on VFD for hot water pump.
Diagnosis: Initial Work Order	HVAC Return Fan (RE-1-T) is making loud squealing noise. The 2T controls for the hot water pump are not working
Diagnostic Fee	\$400
Additional Labor Cost to Perform Repairs	\$640 8hrs @ \$80/hr
Additional Material Cost to Perform Repairs	\$930.56 (See attached detail)
Total Cost of Repair	\$1970.56



WORK ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.		Facility ID:	NY127
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	Mech
E-Mail Address:	adam.cology@tideh2o.net			
Assigned Technician(s):	Patrick Brown			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace motor on return fan (RE-1-T) and fuses on VFD for hot water pump.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			8	\$640.00
Baldo Motor 5HP 3PH 208V	1	\$784.64		\$784.64
Bussmann Fuse, 1A704	6	\$24.32		\$145.92
				\$0.00
				\$0.00
Diagnostic Labor			5	\$400.00
SUB-TOTAL COSTS:		Materials Total	\$930.56	Labor \$1,040.00
			TOTAL	\$1,970.56

F.W. Webb Company
6792 Townline Road
Syracuse, NY 13211
TEL# (315-476-9322)
FAX# (315-472-4139)

Quote
Number
67476375

To:
TIDEWATER, INC.
6625 SELNICK DRIVE

ELKRIDGE MD 21075

SAME
6792 Townline Road

SYRACUSE, NY 13211

(410-540-8700) Fax# (410-579-1685)

Cust #	Customer Po#	Rel#	Writer	Date Req
198314	MOTOR / PAT BROWN		BTW	06/08/20

PAGE 1 OF 1

Quoted By: BRIAN WOLFORD

Quantity	Description	Net Price	Exten	Ln#
1	#BALDOR MOTOR 5HP 3PH 208-2 + GOUH10A34F4BD2S (S3909319) 3 TO 5 DAYS	613.330	613.33	(1)
		Sub Total:	613.33	
		Total:	613.33	

*** NUMBER OF DAYS QUOTE VALID IS 10 ***

PLEASE REFERENCE QUOTE # 67476375 FOR INQUIRIES OR ORDER OF ABOVE MATERIAL

+ THIS PRODUCT IS A SPECIAL ITEM. RESTOCKING FEES MAY APPLY.

BUSSMANN

Fuse, Time Delay, Class RK5, FRS-R Series, 20A

Item # 1A704 Mfr. Model # FRS-R-20 Catalog Page # 177 UNSPSC # 39121604

Web Price i

\$19.00 / each

1

Add to Cart

+ Add to List

 Shipping PickupExpected to arrive **Wed. Jun 10**.

Ship To 43065 (Change)

Shipping Weight 0.15 lbs.

Country of Origin Mexico | Country of Origin is subject to change.

Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order. [More](#) How can we improve our [Product Images](#)? Compare

Product Details

These 600VAC UL Class RK5 fuses are time delay and nonindicating. They tolerate temporary inrush currents without opening, which prevents nuisance-

[View More](#)

