

Additional Funding Request

NY067	CSS# 25199 WO# 8690 Asset# NA											
Description of Repairs	Order Parts and replace flush valves.											
Diagnosis: Initial Work Order	All three urinals do not work in the male latrine on first floor. Appears to be faulty electronic sensors on the flush valves.											
Diagnostic Fee	<p>\$ 160</p> <p>Labor \$80/hr x 2</p>											
Additional Labor Cost to Perform Repairs	<p>\$ 320</p> <p>Labor \$80/hr x 4</p>											
Additional Cost	<p>\$ 726.15</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Manual Flush Valves #5P013 Model Royal 186</td> <td style="width: 15%;">3</td> <td style="width: 15%;">\$225.60</td> <td style="width: 15%;">\$670.80</td> </tr> <tr> <td>TAX</td> <td>3</td> <td>\$16.45</td> <td>\$49.35</td> </tr> </table>				Manual Flush Valves #5P013 Model Royal 186	3	\$225.60	\$670.80	TAX	3	\$16.45	\$49.35
Manual Flush Valves #5P013 Model Royal 186	3	\$225.60	\$670.80									
TAX	3	\$16.45	\$49.35									
Total Cost of Repair	\$ 1,206.15											



WORK ESTIMATE

CSS #: Work Order #:
Emergency Urgent Routine X

Company Name:	Tidewater, Inc.	Facility ID:	NY067
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g.,	First Floor
E-Mail Address:	adam.colopy@tideh2o.net	Classroom/Room #)	
Assigned Technician(s):	Patrick Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

All three urinals do not work in the male latrine on first floor. Appears to be faulty electronic sensors on the flush valves.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Manual Flush Valve 5P013 Model Royal 186	3	\$225.60		\$676.80
Labor			4	\$320.00
Tax	3	\$16.45		\$49.35
SUB-TOTAL COSTS:		Materials Total	\$726.15	Labor \$480.00
		TOTAL		\$1,206.15

SLOAN

Exposed, Top Spud, Manual Flush Valve, For Use With Category Urinals, 1.5 Gallons per Flush

Item # SP013 Mfr. Model # Royal 1B6 Catalog Page # 2752 UNSPSC # 40141609



Web Price

\$188.00 / each

1

Add to Cart

+ Add to List

Shipping

Pickup

Expected to arrive Tue, May 26

Ship To 43065 (Change)

Jump to:

Replacement Parts

Shipping Weight 6.7 lbs.

Country of Origin USA | Country of Origin is subject to change.

Note: Product availability is real time updated and adjusted continuously. The product will be reserved for you when you complete your order. More

How can we improve our Product Images?

Compare

