

Additional Funding Request

VA011	CSS# 25412 WO# 12336 Asset# NA
Description of Repairs	LoCurrent Systems will perform a system update to accommodate recent deployed G&D CAC 7.0
Diagnosis: Initial Work Order	Flash CAC readers with new firmware. Current CAC readers do not recognize newly issued CAC/ID cards
Diagnostic Fee	\$ 0.00
Additional Labor Cost to Perform Repairs	\$ 1,250.00 Labor \$75/hr x 16 and Admin Fee
Additional Cost	\$ 0.00 <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/>
Total Cost of Repair	\$ 1,250.00

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 1573
DATE 06/09/2020

P.O. NUMBER
Culpeper, VA Reader Flash

SALES REP
A LoRusso

	ACTIVITY	QTY	AMOUNT
06/09/2020	Installation Service CSS#25412 WO#12336 Culpeper, VA USARC VA011 Access Control System Update	1	1,250.00

Dear Mr. Grenier:

As per your request, LoCurrent Systems is pleased to provide a quotation to perform System Update to accommodate recent deployed G&D CAC 7.0 at the Culpeper, VA USARC.

Cost Breakdown:

(2) men 8 hours @	
\$75.....	\$1,200.00
Administrative.....	\$50.00

The cost for the above mentioned work is \$1,250.00.

If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.

Thank you.

Sincerely,

Antonietta LoRusso

TOTAL **\$1,250.00**