

Additional Funding Request

VA048	CSS# 25415 WO# 12337 Asset# NA						
Description of Repairs	LoCurrent Systems will perform a system update to accommodate recent deployed G&D CAC 7.0						
Diagnosis: Initial Work Order	Flash CAC readers with new firmware. Current CAC readers do not recognize newly issued CAC/ID cards						
Diagnostic Fee	\$ 0.00						
Additional Labor Cost to Perform Repairs	\$ 1,250.00 Labor \$75/hr x 16 and Admin Fee						
Additional Cost	\$ 0.00 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%; height: 20px;"></td> <td style="width: 12.5%;"></td> <td style="width: 12.5%;"></td> <td style="width: 12.5%;"></td> </tr> </table>						
Total Cost of Repair	\$ 1,250.00						

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 1570
DATE 06/09/2020

P.O. NUMBER

Monteith USARC Reader Flash

SALES REP

A LoRusso

	ACTIVITY	QTY		AMOUNT
06/09/2020	Installation Service CSS#25415 WO#12337 Monteith Center Richmond, VA USARC VA048 Access Control System Update	1	1,250.00	1,250.00

Dear Mr. Colopy:

As per your request, LoCurrent Systems is pleased to provide a quotation to perform System Update to accommodate recent deployed G&D CAC 7.0 at the Monteith Richmond, VA USARC.

Cost Breakdown:

(2) men 8 hours @
\$75.....\$1,200.00
Administrative.....\$50.00

The cost for the above mentioned work is \$1,250.00.

If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.

Thank you.

Sincerely,

Antonietta LoRusso

TOTAL \$1,250.00