

## Additional Funding Request

<b>VA048</b>	<b>CSS# 25658 WO# 12456 Asset# 1463</b>											
Description of Repairs	Replace the Photoeye.											
Diagnosis: Initial Work Order	Gate not working needs repair.											
Diagnostic Fee	\$ 450											
Additional Labor Cost to Perform Repairs	\$ 950 Labor \$75/hr x 12 (2 men 6 each) Admin Fee											
Additional Cost	\$ 250.79 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Photo Safety Eye</td> <td style="width: 15%;">1</td> <td style="width: 20%;">\$232.56</td> <td style="width: 25%;">\$232.56</td> </tr> <tr> <td>Photoeye Hood</td> <td>1</td> <td>\$18.23</td> <td>\$18.23</td> </tr> </table>				Photo Safety Eye	1	\$232.56	\$232.56	Photoeye Hood	1	\$18.23	\$18.23
Photo Safety Eye	1	\$232.56	\$232.56									
Photoeye Hood	1	\$18.23	\$18.23									
Total Cost of Repair	\$ 1,650.79											

**LoCurrent Systems, LLC**

3522 County Highway 11  
 Cooperstown, NY 13326  
 (607)293-7300  
 locurrent@gmail.com



# Estimate

**ADDRESS**

Tidewater Inc.  
 6625- A Selnick Drive  
 Elkridge, MD 21075

**ESTIMATE #** 1595**DATE** 06/25/2020**P.O. NUMBER**

Monteith VA048 Replace Photoeye

	ACTIVITY	QTY	AMOUNT
06/25/2020	<b>Services</b> Follow Up Quotation to Invoice #1682 CSS#25658 WO#12456 Monteith Facility Richmond, VA VA048 Replace Phototeye	1	1,200.79

Dear Ms. Lee:

LoCurrent Systems is pleased to provide a Quotation to replace the Photoeye at the Monteith Facility Gate Operator Richmond, VA VA048.

Cost Breakdown:

(1) Photo Safety Eye.....	\$232.56
(1) Photoeye Hood.....	\$18.23
Administrative.....	\$50.00
(2) men 6 hrs @ \$75.....	\$900.00

Grand Total.....	\$1,200.79
------------------	------------

The cost for the above mentioned work is  
 \$1,200.79

TOTAL

**\$1,200.79**

**LoCurrent Systems, LLC**

3522 County Highway 11  
Cooperstown, NY 13326  
(607)293-7300  
locurrent@gmail.com



# INVOICE

**BILL TO**

Tidewater Inc.  
6625- A Selnick Drive  
Elkridge, MD 21075

**INVOICE #** 1682  
**DATE** 06/25/2020  
**DUE DATE** 07/25/2020  
**TERMS** Net 30

**P.O. NUMBER**

Monteith VA048 Diagnose GateOp

DESCRIPTION	QTY	RATE	AMOUNT
<b>Services</b>	1	450.00	450.00
As per Estimate #1594:			
CSS#25658 WO#12456			
Monteith Facility Richmond, VA USARC VA048			
Diagnose Gate Operator			

Dear Ms. Lee:

As per your request LoCurrent Systems is pleased to provide a quotation to diagnose the Gate Operator at the Monteith Facility Richmond, VA USARC VA048.

The cost to diagnose is \$450.00.

Thank you for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

If you have any questions regarding this invoice, please contact Antonietta LoRusso at (607)293-7300.

BALANCE DUE

**\$450.00**

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: **VA048**

Date of Visit: 6-24-2020

Contractor Personnel on Site:

1. <u>Nick LoRusso</u>	4. Estimate #1594
2. <u>Ken Stahl</u>	5. Invoice #1682
3. <u>Wade Stahl</u>	6. _____

**Service Call Number**

CSS# 25415 WO# +2337  
25658 12456

**Description of Repairs**

Inspect and diagnose non functional Gate operator. Recommending New Photo Eye, existing one has water in it.

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Nick LoRusso Date: 6-24-2020

Signed: LoRusso

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: No Available Personnel Date: 6-24-2020

Signed: \_\_\_\_\_

E-Mail: \_\_\_\_\_