

## Additional Funding Request

<b>DE002</b>	<b>CSS 25853 WO# 12746 Asset# NA</b>							
Description of Repairs	SS to remove and replace the third air line hose that is leaking, replace the regulator and connection hose as well, then perform a system check to ensure that everything is working properly.							
Diagnosis: Initial Work Order	A third airline hose is no longer working due to a leak. This is not the same as a previous ticket (FIS #25853) for the other two air lines.							
Diagnostic Fee	\$ 400							
Additional Labor Cost to Perform Repairs	\$ 1,400 Labor \$100/ hr x 14							
Additional Cost	\$ 332.77 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Parts (Detail in quote)</td> <td style="width: 10%;">1</td> <td style="width: 20%;">\$575.00</td> <td style="width: 30%;">\$575.00</td> </tr> </table>				Parts (Detail in quote)	1	\$575.00	\$575.00
Parts (Detail in quote)	1	\$575.00	\$575.00					
Total Cost of Repair	\$ 2,132.77							



**S&S MECHANICAL**

**S&S Mechanical**  
4845 South Crain Highway  
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555  
Fax. 1 - (301) 574-1558  
[www.sandsmidatlantic.com](http://www.sandsmidatlantic.com)

## CUSTOMER QUOTATION NO. 383

Tidewater, Inc.  
Tidewater, Inc  
6625 Selnick Dr.  
Suite A  
Elkridge MD 21075

**Quote Name:** 12746  
**Quote No:** 383  
**Site:** DE002 Savannah Road  
**Site Contact:**  
**Salesperson:** Lindsay Ruby  
**Created Date:** 09/21/2020  
**Valid For:** 30 Day(s)

**WO#:** 12746

**CSS 25823**

**Problem:** A third airline hose is no longer working due to a leak. This is not the same as a previous ticket (FIS #25853) for two other of the air lines.

S&S proposes to furnish and install the following:

S&S proposes to remove and replace the third airline hose that is leaking.

S&S will replace the regulator and connection hose as well.

S&S will then perform a system check to ensure everything is working properly.

### Service

Item	Quantity	Unit Price	Total
Air Hose/ 5Z331	1.00	\$110.40	\$110.40
Regulator/ G7060159	1.00	\$216.98	\$216.98
3/8" x 3' Air Hose Lead	1.00	\$5.39	\$5.39
Diagnosis Fee	1	\$400.00	\$400.00
Plumbing Labor Rate	14	\$100.00	\$1,400.00
		<b>Sub-Total ex Tax</b>	\$2,132.77
		<b>Tax</b>	\$0.00
		<b>Total inc Tax</b>	\$2,132.77

<b>Labor</b>	\$1,800.00
<b>Materials</b>	\$332.77
<b>Sub-Total ex Tax</b>	\$2,132.77
<b>Tax</b>	\$0.00
<b>Total inc Tax</b>	\$2,132.77

1:56



[harborfreight.com](https://www.harborfreight.com)

## CENTRAL PNEUMATIC

# 3/8 In. X 3 Ft. Air Hose Lead

(421) [Write a Review](#)




Connect an air hose reel to a compressor with this air hose lead

**\$449**

1

**Add to Cart**



Search by keyword or model #

≡ Shop Categories

Get Fast, Free Shipping. See How.

Home / Paint, Coatings & Supplies / Parts / Paint Sprayer Parts



Hover or click to zoom



Help us improve our product images

SHARPE MANUFACTURING

## Air Control Unit for Model 880A

Zoro #: G7060159 Mfr #: 6950



No Reviews | [Write the First Review](#)

**\$180.82**

- Item: Air Control Unit for Model 880A
- Country of Origin (subject to change): China

[See full product details](#)

[Specifications](#) | [Description](#) | [Reviews](#)

You May Also

