

**Additional Funding Request**  
**INVOICE**

<b>MD024</b>	<b>CSS# 25846 WO# 13948 Asset# NA</b>							
Description of Repairs	Arrived on site to find Reader and Weathershield to be completely destroyed, appeared to have been struck by vehicle. Replaced Reader and Weathershield with new while on site.							
Diagnosis: Initial Work Order	Main gate 1, CAC reader inop, gate access unavailable. Repair Reader.							
Diagnostic Fee	\$ 0							
Additional Labor Cost to Perform Repairs	<p>\$ 350</p> <p>LoCurrent Labor \$150/hr x 2</p> <p>Admin Fee \$50</p>							
Additional Cost	<p>\$ 1660</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 2px;">Parts</td> <td style="padding: 2px;">2</td> <td style="padding: 2px;">1660</td> <td style="padding: 2px;">1660</td> </tr> </table>				Parts	2	1660	1660
Parts	2	1660	1660					
Total Cost of Repair	\$ 2010							

**LoCurrent Systems, LLC**

3522 County Highway 11  
 Cooperstown, NY 13326  
 (607)293-7300  
 locurrent@gmail.com



# INVOICE

**BILL TO**

Tidewater Inc.  
 6625- A Selnick Drive  
 Elkridge, MD 21075

**INVOICE #** 1876  
**DATE** 03/17/2021  
**DUE DATE** 04/16/2021  
**TERMS** Net 30

**P.O. NUMBER**

AMSA 83 Diagnose Main Gate 1

ACTIVITY	QTY	RATE	AMOUNT
<b>Services</b>			
As per Estimate #1752:	1	2,010.00	2,010.00
CSS#25864 WO#13948			
AMSA 83 Baltimore, MD USARC MD024			

Dear Ms. Lowery:

As per your request, LoCurrent Systems is pleased to provide a quotation to diagnose the issues being experienced at the Main Gate 1 at the Baltimore, MD MD024 AMSA 83 Facility as per provided SOW- Main gate 1, CAC reader inop, gate access unavailable. Repair reader.

Arrived on site to find Reader and Weathershield to be completely destroyed, appeared to have been struck by vehicle. Replaced Reader and Weathershield with new while on site. (Waiving Diagnostic Fee)

Cost Breakdown:

(1) Veridt Reader.....\$1,450.00

(1) Weathershield.....\$210.00

(2) men 2 hours.....\$300.00

Administrative.....\$50.00

Grand Total.....\$2,010.00

Cost to diagnose above mentioned is \$2,010.00.

Thank you for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

If you have any questions regarding this invoice, please contact Antonietta  
LoRusso at (607)293-7300.

BALANCE DUE

**\$2,010.00**

**CERTIFICATION OF WORK**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MDO24

Date of Visit: 3-17-21

Contractor Personnel on Site:

1. Keith Pearson
2. Logan Docus
3. \_\_\_\_\_

4. \_\_\_\_\_
5. \_\_\_\_\_
6. \_\_\_\_\_

**Service Calls – Service Call Number and Description**

1. CSS # 25864
2. WO # 13948
3. EST # 1752

Replaced reader & wethershield w/ new old  
**CERTIFICATION OF WORK**  
ones were missing

To be signed by the Contractor:

Print Name: Keith Pearson Date: 3-17-21  
Signed: Keith Pearson

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Mark Smith W3-10 Date: 20210317  
Signed: Mark Smith

E-Mail: mark.smith.civ@mail.mil









Curtis Bay  
US Army Reserve

Area Maintenance  
Support Activity

700 East Ordnance Rd  
Baltimore, Maryland

**CURRENT  
FPCON  
LEVEL  
BRAVO**



INSERT CARD

#

0

\*

6

8

7

6

5

4

3

2

1

NO  
ENTRY

CARD  
PLACE

ENTER

PLACE FINGER