

Additional Funding Request

MD002	CSS# 25883 WO# 14159 Date 5/11/21			
Description of Repairs	Labor and materials to replace 20 bulbs and 5 ballasts.			
Diagnosis: Initial Work Order	Repair 4x fluorescent tubes in 1st floor hallway, 8x in female latrine 1st floor, bldg 001.			
Diagnostic Fee	\$ 160 Labor \$80/hr x 2			
Additional Labor Cost to Perform Repairs	\$ 480 Labor \$80/hr x 6			
Additional Material Cost to Perform Repairs	\$ 339.70			
	Linear LED Bulbs	20	11.24	224.80
	Centium ™ Electronic Fluorescent Ballasts	5	22.98	114.90
Total Cost of Repair	\$ 979.70			



WORK ESTIMATE

CSS #:

25883

Work Order #:

14159

Emergency

Urgent

Routine

X

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace 20 bulbs and 5 ballasts.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagostic			2	\$160.00
Linear LED Bulbs	20	\$11.24		\$224.80
Centium TM , Electronic Fluorescent Ballast	5	\$22.98		\$114.90
Labor			6	\$480.00
SUB-TOTAL COSTS:		Materials Total	\$339.70	Labor \$640.00
TOTAL			\$979.70	

Cart


Submit Order

PO Number

Optional

My Products


Reference...nformation ☐



GE CURRENT

Linear LED Bulb, UL Type A, T8, Medium Bi-Pin (G13), 5, 000 K Color

Item # **467W20**



Qty
20

Your Price
\$8.92 / each

Total **\$178.40**

Availability

Expected to arrive **Wed. May 12.**

Remove

ADVANCE

Cart

Submit Order

Remove



ADVANCE
Centium(TM), Electronic,
Fluorescent Ballast,
Ballast Start Type Instant

Item # **2MCX5**



Qty

5

Your Price
\$18.24 / each

Total **\$91.20**

Availability
Expected to arrive **Wed. May 12.**

Remove

Delivery Method

☒ Shipping



