

**Region:** 5

**Location:** NY067

**CSS #:** 26343

**Maximo Work Order No.:** 10250

**Asset #:** NA

**Date Issued:** 08/20/2020

**Original Description:** Motorized gate in MEP Lot does not open.

**Repairs Needed:**

Found the following issues on site: Blown out CPU, Strike on Motor Pool main door, Reader at Gate, BlackBox Copper to Ethernet Communicators also found Gate bumper Module in Gate Operator to be bad. Replaced All damage equipment to achieve a fully functional System

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
1	NA	Parts see detail on Invoice	--	--	\$2,314.81	--	\$ 2,314.81
--		Labor 2 men 8 hrs each	16	\$75.00	--	--	\$ 1,200.00
--	NA	TW Oversite and Coordination	2	\$80.00	--	--	\$ 160.00

**Estimate Summary:**

Labor Hours	Labor Cost	Material Cost		Total Cost	CE Factor	Total Estimate
18	\$ 1,360.00	\$ 2,314.81		\$3,674.81	103%	<b>\$3,785.05</b>

**LoCurrent Systems, LLC**

3522 County Highway 11  
 Cooperstown, NY 13326  
 (607)293-7300  
 locurrent@gmail.com



# INVOICE

**BILL TO**

Tidewater Inc.  
 6625- A Selnick Drive  
 Elkridge, MD 21075

**INVOICE #** 1739  
**DATE** 08/26/2020  
**DUE DATE** 09/25/2020  
**TERMS** Net 30

**P.O. NUMBER**

EMERGENCY Utica NY067

DESCRIPTION	QTY	RATE	AMOUNT
<b>Installation</b>	1	3,514.81	3,514.81
Emergency Call			
CSS#26343 WO#10250			
Utica, NY USARC NY067			
Diagnose & Repair MEP Gate Operator			

Dear Ms. Lee:

Diagnosed & repaired issues being experienced at the Utica, NY USARC. Found the following issues on site: Blown out CPU, Strike on Motor Pool Main Door, Reader at Gate, Black Box Copper to Ethernet Communicators also found Gate Bumper Module in Gate Operator to be bad. Replaced all damaged equipment to achieve a fully functional System.

Cost Breakdown:

(1) Galaxy CPU Board.....\$382.20

(1) 9600 Door Strike.....\$353.00

(1) Black Box Ethernet Extender.....\$329.61

Veridt Biometric Card Reader.....\$1,450.00

Veridt Reader Core Rebate.....(\$200.00)

(2) men 8 hours @ \$75.....\$1,200.00

Grand Total.....\$3,514.81

The total cost to repair System is \$3,514.81.

Thank you for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

If you have any questions regarding this invoice, please contact Antonietta  
LoRusso at (607)293-7300.

BALANCE DUE

**\$3,514.81**