

Additional Funding Request

Invoice

MD003	CSS# 27313 WO# 13121 Asset# NA
Description of Repairs	Changed combo, cleaned threshold, and greased panel on vault door
Diagnosis: Initial Work Order	Vault door will not lock
Diagnostic Fee	\$0
Additional Labor Cost to Perform Repairs	\$ 455 Advanced Labor (see attached invoice)
Additional Material Cost to Perform Repairs	\$0
Total Cost of Repair	\$ 455.00



6318 Reisterstown Rd
Baltimore, MD 21215
(410) 764-2001
Billing2@ampmlock.com

Invoice

DATE	10/22/2020
INVOICE#	1200
TERMS	Due Upon Receipt
DUE DATE	10/22/2020

BILL TO
Tidewater PM 3761 Attucks Drive Powell OH 43065 (703) 738-5301

PRIMARY SERVICE LOCATION
Tidewater PM 5515 Liberty Heights Avenue Baltimore MD 21207 (787) 354-8633

JOB#	DATE	PO/REF#	DESCRIPTION
1325	10/22/2020	WO# 13121	
Print Name (Signature):			
Job Charges		Qty	Rate
Service Call		1.00	\$95.00
Labor		2.00	\$120.00
Clean Threshold			\$240.00
Grease Panal			
Change Combo		1.00	\$120.00
Job Subtotal			\$455.00
Job Total			\$455.00

PRE-WORK SIGNATURE

POST-WORK SIGNATURE



10/22/2020 10:26 am

CUSTOMER MESSAGE

Advanced Security Safe & Lock's One Year Warranty on recalls only covers parts and services/labor when the part is provided by Advanced Security Safe & Lock. Service/labor on parts not provided by Advanced Security Safe & Lock or if the parts have passed the one year warranty time period are NOT covered under Advanced Security Safe & Lock's One Year Warranty. Late payments are subject to fees.

Invoice Total:	\$455.00
Deposits (-):	\$0.00
Payments (-):	\$0.00
Total Due:	\$455.00

CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: MD003 Date of Visit: 10/22/20

Contractor Personnel on Site:

1. Advanced Security 4. _____
2. _____ 5. _____
3. _____ 6. _____

Service Call Number

CSS# TBD WO# 13121

Description of Repairs

Change Combo


Clear Threshold

Grease Panel

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Bon Cullin Date: 10/22/2020

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Nicholas R Cruz SGT Date: 10/22/2020

Signed: 

E-Mail: Nicholas.r.Cruz5.mil@mail.mil






**RESTRICTED
WARNING**

THIS FACILITY HAS BEEN DECLARED A RESTRICTED AREA
AUTHORITY OF THE COMMANDER IN ACCORDANCE WITH THE
VISIONS OF THE DIRECTIVE ISSUED BY THE SECRETARY OF DEFENSE
ON 20 AUGUST 1954, PURSUANT TO THE PROVISIONS OF THE
INTERNAL SECURITY ACT OF 1950. UNAUTHORIZED PERSONS
PROHIBITED. ALL PERSONS AND VEHICLES ENTERING
LIALE TO SEARCH, PHOTOGRAPHING, MAKING NOTES,
MAPS OR GRAPHIC REPRESENTATIONS OF THIS AREA
ACTIVITIES, IS PROHIBITED UNLESS SPECIFICALLY AUTHORIZED
BY THE COMMANDING OFFICER. ANY SUCH MATERIAL
THE POSSESSION OF UNAUTHORIZED PERSONS WILL BE
FISCATED.









PROTECTION
THIS IS A U.S. GOVERNMENT CLASS 5 VAULT DOOR
WHICH HAS BEEN TESTED AND APPROVED BY THE
GOVERNMENT UNDER FEDERAL SPEC. AA-0-800.
IT AFFORDS THE FOLLOWING SECURITY
PROTECTION:
28 MAN HOURS AGAINST SUBSIDIPIOUS ENTRY
28 MAN MINUTES AGAINST COVERT ENTRY
18 MAN MINUTES AGAINST FORCED ENTRY
THE PROTECTION CERTIFIED ABOVE APPLIES ONLY
TO THE DOOR AND NOT THE VAULT PROPER.

SF-700 WH-1
247730

LOCK POSITION
1. OPEN POSITION: Position of the lock when the door is open.
2. SHUT POSITION: Position of the lock when the door is closed.
3. LOCKED POSITION: Position of the lock when the door is closed and locked.
4. UNLOCKED POSITION: Position of the lock when the door is closed and unlocked.
5. RELOCK POSITION: Position of the lock when the door is closed and locked again.
6. REUNLOCK POSITION: Position of the lock when the door is closed and unlocked again.

