

## Additional Funding Request

|   |  |        |        |                               |   |        |        |
|---|--|--------|--------|-------------------------------|---|--------|--------|
| <b>VA099</b>                                | <b>CSS# 27986 WO# 13319 Asset# NA</b>  |        |        |                               |   |        |        |
| Description of Repairs                      | Remove and install the new ignition assembly and ignition lead. Start, test, and ensure proper operation of the system.  |        |        |                               |   |        |        |
| Diagnosis:<br>Initial Work Order            | The #1 Boiler is failing to ignite the burner - Associated Asset ID number - - Description of equipment or system - Hot Water Boiler   |        |        |                               |   |        |        |
| Diagnostic Fee                              | \$ 480<br>Labor 4/hour x \$120.00  |        |        |                               |   |        |        |
| Additional Labor Cost to Perform Repairs    | \$ 480<br><br>Labor 4/hr x \$120.00  |        |        |                               |   |        |        |
| Additional Material Cost to Perform Repairs | <div style="display: flex; align-items: flex-start;"> <div style="margin-right: 10px;">\$ 161.98</div> <table border="1" style="border-collapse: collapse; width: 100%;"> <tr> <td style="padding: 2px;">Parts (See quote for details)</td><td style="text-align: center; padding: 2px;">1</td><td style="text-align: right; padding: 2px;">161.98</td><td style="text-align: right; padding: 2px;">161.98</td></tr> </table> </div> |        |        | Parts (See quote for details) | 1 | 161.98 | 161.98 |
| Parts (See quote for details)               | 1  | 161.98 | 161.98 |                               |   |        |        |
| Total Cost of Repair                        | \$ 1,121.98  |        |        |                               |   |        |        |



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

## Proposal

December 11, 2020

Quotes are valid for 30 days.

USARC - VA099 Bedford  
1117 Harmony Lane  
Bedford VA 24523  
Email

[tina.lee@tideh2o.net](mailto:tina.lee@tideh2o.net)

Contact Name Tina Lee & Adam Colopy  
Telephone 0.00  
Cell Phone 614-623-9569  
Fax Number 0.00

### DESCRIPTION OF EQUIPMENT:

HWB-1  
LOCHINVAR MODEL KBN400,  
S/N K12H10234409  
WO 13319 / CSS 27986

### DESCRIPTION OF PROBLEM:

While onsite, our technician Howard Floyd the boiler ignition probe was loose in the ceramic insulator and unable to be securely tightened. Tech recommends replacing the ignition assembly and ignition lead to ensure proper operation of the system.

### DESCRIPTION OF REPAIRS:

Remove and install the new ignition assembly and ignition lead. Start, test, and ensure proper operation of the system.

### MATERIAL, EQUIP OR PARTS

Lochinvar Ignitor Assembly P/N 100165929  
Lochinvar Ignition Lead P/N 100208618  
Shipping  
Truck Fee

| Quantity              | Sell price       |
|-----------------------|------------------|
| 1.00                  | \$ 34.37         |
| 1.00                  | \$ 42.61         |
| 1.00                  | \$ 30.00         |
| 1.00                  | \$ 55.00         |
| <b>Material Total</b> | <b>\$ 161.98</b> |

### LABOR ITEMIZED

Labor - Incurred 4  
Labor - One Man 4  
Labor - Second Man 0

|                    | Labor            |
|--------------------|------------------|
| \$ 120.00          | \$ 480.00        |
| \$ 120.00          | \$ 480.00        |
| \$ 120.00          | \$ -             |
| <b>Labor Total</b> | <b>\$ 960.00</b> |

Thank you for your business. If you have any questions or concerns, please feel free to contact us via telephone or [quotes@mooreselectric.com](mailto:quotes@mooreselectric.com)

|                  |                    |
|------------------|--------------------|
| <b>Materials</b> | <b>\$ 161.98</b>   |
| <b>Labor</b>     | <b>\$ 960.00</b>   |
| <b>TOTAL</b>     | <b>\$ 1,121.98</b> |

*This does not include  
original call cost.*

Robert Lowery, Changeout Estimator 434-309-2591  
Ian Harris, Estimator 434-309-2497  
James Davis, Estimator 434-309-2568  
Marvin Slaughter, Estimator 434-369-3514  
Jared Underwood, Estimator 434-306-2446

Approved by: \_\_\_\_\_

#### Standard Terms and Conditions

Payments past 30 days are subject to 1.5% monthly service charge on unpaid balance. Additional charges for payments made through credit cards may apply. Late payments sent to collections or legal process the purchaser agrees to pay all costs, expenses, and reasonable attorney fees.

# QUOTATION

Southern Refrigeration Corporation  
1620 Wythe Rd.  
Lynchburg, VA 24501  
US

|                    |        |
|--------------------|--------|
| Order Number       |        |
| 10077585           |        |
| Order Date         | Page   |
| 12/8/2020 11:02:06 | 1 of 1 |

Quote Expires On 1/7/2021

**Bill To:**

MOORE'S ELECTRIC  
PO BOX 119  
ALTAVISTA , VA 24517  
US

**Ship To:**

MOORE'S ELECTRIC  
101 EDGEWOOD AVE  
ALTAVISTA , VA 24517  
US

Requested By: HOWARD FLOYD

**Customer ID:** 13336

| <i>PO Number</i>  |                  |                  |            |              | <i>Taker</i>            |                |              |                 |
|-------------------|------------------|------------------|------------|--------------|-------------------------|----------------|--------------|-----------------|
| LOCHINVAR PARTS   |                  |                  |            |              | MMOORE                  |                |              |                 |
| <i>Quantities</i> |                  |                  |            |              | <i>Item ID</i>          | <i>Pricing</i> | <i>Unit</i>  | <i>Extended</i> |
| <i>Ordered</i>    | <i>Allocated</i> | <i>Remaining</i> | <i>UOM</i> | <i>Disp.</i> | <i>Item Description</i> | <i>UOM</i>     | <i>Price</i> | <i>Price</i>    |

**4-5 DAY LEAD, PLUS FREIGHT. HOWARD 444-2199.**

|                                       |   |   |    |  |           |    |       |       |
|---------------------------------------|---|---|----|--|-----------|----|-------|-------|
| 1                                     | 0 | 1 | EA |  | 100165929 | EA | 28.64 | 28.64 |
| LOCHINVAR IGNITOR<br>INCLUDES GASKET. |   |   |    |  |           |    |       |       |
| 1                                     | 0 | 1 | EA |  | 100208618 | EA | 35.51 | 35.51 |
| LOCHINVAR IGNITION WIRE               |   |   |    |  |           |    |       |       |

Total Lines: 2

**SUB-TOTAL:** 64.15  
**TAX:** 3.41  
**AMOUNT DUE:** 67.56  
U.S. Dollars