

Region: 2

Location: NY039

CSS #: 28071

Maximo Work Order No.: 11905

Asset #:

Date Issued: 2/5/21

Original Description:

Repair Air handler on right side of building. Motor appears to be burned out. Coil is leaking urgent

Repairs Needed:

Install new Trane air handling unit to replace existing Trane Climate Changer M# LZ-35 S# K5M301280. To include Demo of the old unit, remove and dispose. Set new unit in place and make all necessary connections. Replacement unit using 2.5" double wall insulated construction; galvanized steel with mill finish, approx. 134" L x 117" W x 86" H plus 6" base rail; Inlet mixing box section with dampers; filter rack and filters; (3) ECM supply fans wired to external junction box; control box with motor protection and low voltage terminals for field installation. ECM fans have interfral speed control (no VFD required); coil section with chilled water coils and stainless steel drain pans; hot deck section with heating coil; front outlet MZ damper

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Hyde-Stone Mechanical	--	--	--	--	\$174,096.00
--	NA	Tidewater Site Coordination and Project Oversight	80	80	--	--	\$6,400.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
--	--	--	--	\$180,496.00	103%	\$185,910.88

Hyde-Stone Mechanical

Contractors, Inc. 22962 Murrock Circle
Watertown, NY 13601
315-788-1300 Fax 315-788-9646

To: TIDE WATER, INC
6625 SELNICK DRIVE, SUITE A

ELKRIDGE, MD 21075

QUOTATION

Quote #: 0000000493-000 (Preview)
Quote Type: Work Order
Reference:
Cross Ref:
Work Order: n/a
Customer: 922
Terr/sale: HSE
Current Date: Mar 10, 2021
Expiry Date: N/A

Work Address: 6625 SELNICK DRIVE, SUITE A
ELKRIDGE, MD
21075



