

## Additional Funding Request

<b>NY035</b>	<b>CSS# 28122 WO# 11130 Asset# NA</b>							
Description of Repairs	Labor and materials to install new pilot assembly on boiler.							
Diagnosis: Initial Work Order	Repair Heating Boiler on left side of mechanical room. Boiler will not fire.							
Diagnostic Fee	<p>\$ 240</p> <p>Labor \$80/hr x 3</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 480</p> <p>Labor \$80/hr x 6</p>							
Additional Material Cost to Perform Repairs	<p>\$ 720.13</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Pilot Assembly</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 10%; text-align: center;">720.13</td> <td style="width: 10%; text-align: center;">720.13</td> </tr> </table>				Pilot Assembly	1	720.13	720.13
Pilot Assembly	1	720.13	720.13					
Total Cost of Repair	\$ 1,440.13							



# WORK ESTIMATE

CSS #:

28122

Work Order #:

11130

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	NY035
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	<a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a>		
Assigned Technician(s):	Patrick Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to install new pilot assembly on boiler.

LABOR/MATERIAL		MATERIAL/SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Labor			6	\$480.00
Pilot Assembly	1	\$720.13		\$720.13
				\$0.00
				\$0.00
				\$0.00
				\$0.00
Diagnostic Labor			3	\$240.00
SUB-TOTAL COSTS:		Materials Total	\$720.13	Labor \$720.00
TOTAL				\$1,440.13

**Hyde Stone Mechanical Contractors**

22962 Murrock Circle  
Watertown, NY 13601  
315-788-1300 Fax 315-788-9646

**To:** TIDE WATER, INC  
6625 SELNICK DRIVE, SUITE A  
  
**Attn:** ELKRIDGE, MD 21075  
PATRICK BROWN

**Work Address:** U.S. ARMY RESERVE - TIDE WATER  
420 ELECTRONICS PARKWAY  
LIVERPOOL, NY  
13088

**QUOTATION**

**Quote #:** 0000000308-000  
**Quote Type:** Work Order  
**Reference:** PATRICK BROWN  
**Cross Ref:**  
**Work Order:** n/a  
**Customer:** USARMYLPTW  
**Terr/sale:** HSE  
**Current Date:** Dec 18, 2020  
**Expiry Date:** N/A

Code	Description	Quantity	UOM	Price	Total
The pricing you requested to purchase a pilot assembly for a Power Flame Burner, Model No JR15A-10, Serial # 051994914 is shown below. Please call me at extension #236 if you have any questions. Thank you.					
N/A	PILOT ASSEMBLY	1.00	EA	562.60	562.60
				<b>Sub Total</b>	562.60
				<b>Tax (562.60)</b>	45.01
				<b>Total Quotation</b>	607.61



