

Additional Funding Request

MD002	CSS# 28571 WO# 13627 Asset# NA							
Description of Repairs	Labor and material to replace security boxes around 2 thermostats in building 0314.							
Diagnosis: Initial Work Order	Repair security boxes around thermostats, 2x, bldg 0314.							
Diagnostic Fee	<p>\$ 160</p> <p>Labor \$80/hr x 2</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 200</p> <p>Labor \$80/hr x 2.5</p>							
Additional Material Cost to Perform Repairs	<p>\$ 96.40</p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>Plastic Universal Thermostat Guard</td> <td>2</td> <td>96.40</td> <td>96.40</td> </tr> </table>				Plastic Universal Thermostat Guard	2	96.40	96.40
Plastic Universal Thermostat Guard	2	96.40	96.40					
Total Cost of Repair	\$ 456.40							



WORK ESTIMATE

CSS #: 28571

Work Order #: 13627

Emergency Urgent Routine X

Company Name:	Tidewater, Inc.		Facility ID:	MD002
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.cology@tideh2o.net			
Assigned Technician(s):	John Brown			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and material to replace security boxes around 2 thermostats in building 0314.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Parts See detail in quote	2	\$48.20		\$96.40
Labor			2.5	\$200.00
SUB-TOTAL COSTS:		Materials Total	\$96.40	Labor \$360.00
			TOTAL	\$456.40

[Back](#)


Details



GRAINGER APPROVED Plastic Universal Thermostat Guard, Off-White

Item # 4E649

Mfr Model # 4E649



ZOOM



Qty

 Your Price

\$38.25 / each

[ADD TO CART](#)[ADD TO LIST](#)

Availability

Shipping (Default)

Expected to arrive **Tue. Feb 09.**

Home



Cart



Account



Branches

...

More



DO NOT ADJUST

