

**Region:** 2

**Location:** NY039

**CSS #:** 28889

**Maximo Work Order No.:** 11910

**Asset #:**

**Date Issued:** 2/8/21

**Original Description:**

Repair wet ceiling tile (multiple).

**Repairs Needed:**

Labor & materials to replace ceiling tiles & fluorescent light bulbs.

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Materials (See attached detail)	--	--	\$8,484.02	--	\$8,484.02
--	NA	Tidewater Labor (Includes Diagnostic)	50	\$80.00	--	--	\$4,000.00

**Estimate Summary:**

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
50	\$4,000.00	\$8,484.02		\$12,484.02	103%	<b>\$12,858.54</b>



# WORK ESTIMATE

CSS #:

Work Order #:

Emergency  Urgent  X  Routine

Company Name:	Tidewater, Inc.	Facility ID:	NY039
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	<a href="mailto:adam.colopy@tideh2o.net">adam.colopy@tideh2o.net</a>		
Assigned Technician(s):	Patrick Brown		

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor & materials to replace ceiling tiles and fluorescent light bulbs.

LABOR/MATERIAL		MATERIAL/SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Parts (See detail in quote)	1	\$8,484.02		\$8,484.02
Labor			48	\$3,840.00
SUB-TOTAL COSTS:		Materials Total	\$8,484.02	Labor \$4,000.00
		TOTAL	\$12,484.02	

**Delivery Method**

Shipping

Pickup

**Find A Branch**

Enter an address, city & state, ZIP code, branch # or country. ?

**Go**

**My Selected Branch**

**East Syracuse Branch #816**  
6285 E. Molloy Rd. East Syracuse, NY 13057

**PHONE**  
1-800-472-4643

**HOURS**  
M-F 7:00 AM - 4:00 PM Eastern

**Proceed to Checkout**

**Order Summary**

Subtotal	\$6,628.14
<b>Estimated Total</b>	<b>\$6,628.14</b>

Availability, shipping, tax & promotions are not final until you complete your order.

**Add Promotional Code**

## My Products

Show Reference Information | Clear Cart

 <b>ARMSTRONG</b> <b>Ceiling Tile, Width 24 in, Length 48 in, 3/4 in Thickness, Mineral Fiber, PK 10</b>  Item # <b>5NGJ9</b> Price <b>\$126.81 / pkg. of 10</b>  This item requires special shipping, additional charges may apply.	<b>Availability</b> Available for pickup <b>Tue. Feb 09</b> estimated after 8:30 AM.	<input type="text" value="34"/> <small>Qty</small> <small>Update</small> <small>Remove</small>	<b>TOTAL</b> <b>\$4,311.54</b>
 <b>GE CURRENT</b> <b>Linear Fluorescent Bulb, T12, Medium Bi-Pin (G13), Lumens 2,130 lm, 4,100 K Color Temperature</b>  Item # <b>4WX02</b> Price <b>\$14.12 / each</b> Shipping: pkg of 30	<b>Availability</b> Available for pickup <b>Tue. Feb 09</b> estimated after 8:30 AM.	<input type="text" value="90"/> <small>Qty</small> <small>Update</small> <small>Remove</small>	<b>TOTAL</b> <b>\$1,270.80</b>
 <b>PHILIPS</b> <b>Linear Fluorescent Bulb, T8, Medium Bi-Pin (G13), Lumens 2,625 lm, 3,500 K Color Temperature</b>  Item # <b>492X84</b> Price <b>\$17.43 / each</b> Shipping: pkg of 30	<b>Availability</b> Available for pickup <b>Wed. Feb 10</b> estimated after 11:00 AM.	<input type="text" value="60"/> <small>Qty</small> <small>Update</small> <small>Remove</small>	<b>TOTAL</b> <b>\$1,045.80</b>

If you changed multiple quantities, Update All.



