

Additional Funding Request

VA701	CSS# 29170 WO# 13450 Asset# NA							
Description of Repairs	Labor and material to replace 9 light pole handhole covers with brackets.							
Diagnosis: Initial Work Order	The LED light pole hand access covers need repaired							
Diagnostic Fee	<p>\$ 160</p> <p>Labor \$80/hr x 2</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 640</p> <p>Labor \$80/hr x 8</p>							
Additional Material Cost to Perform Repairs	<p>\$ 691.74</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">3" x 5" Oval Hand Hole Cover w/ Bracket</td> <td style="width: 10%;">9</td> <td style="width: 10%;">76.86</td> <td style="width: 10%;">691.74</td> </tr> </table>				3" x 5" Oval Hand Hole Cover w/ Bracket	9	76.86	691.74
3" x 5" Oval Hand Hole Cover w/ Bracket	9	76.86	691.74					
Total Cost of Repair	\$ 1491.40							



WORK ESTIMATE

CSS #: 29170

Work Order #: 13450

Emergency

Urgent

Routine X

Company Name:	Tidewater, Inc.		Facility ID:	VA701
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.cology@tideh2o.net			
Assigned Technician(s):	Richard Walker			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor & material to replace 9 light pole handhole covers with brackets.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
3" x 5" Oval Hand Hole Cover With Bracket	9	\$76.86		\$691.74
Labor			8	\$640.00
SUB-TOTAL COSTS:		Materials Total	\$691.40	Labor \$800.00
			TOTAL	\$1,491.40



3" x 5" Oval Hand Hole Cover with Bracket

Color: Black (Standard)

Change

Contact us for current lead times.

SKU : JM-HHC-OB-3050-BK

9



Item Price : **\$61.00**

Item Total : **\$549.00**

Remove

Subtotal: \$549.00

ESTIMATE SHIPPING & TAX



