

## Additional Funding Request

<b>MD019</b>	<b>CSS# 29281 WO# 13852 Asset# NA</b>							
Description of Repairs	Labor and material to replace 40 bulbs and 12 ballasts at MD019.							
Diagnosis: Initial Work Order	There are numerous lights out in the building. The reason is not known at this time. There are 12 lights out in room 205 and 10 that are out in room 209							
Diagnostic Fee	<p>\$ 240</p> <p>Labor \$80/hr x 3</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 640</p> <p>Labor \$80/hr x 8</p>							
Additional Material Cost to Perform Repairs	<p>\$ 1616.84</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Parts</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 20%; text-align: center;">1616.84</td> <td style="width: 30%; text-align: center;">1616.84</td> </tr> </table>				Parts	1	1616.84	1616.84
Parts	1	1616.84	1616.84					
Total Cost of Repair	\$ 2496.84							



# WORK ESTIMATE

CSS #: 29281

Work Order #: 13852

Emergency  

Urgent  

Routine X

Company Name:	Tidewater, Inc.		Facility ID:	MD019
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	<a href="mailto:adam.cology@tideh2o.net">adam.cology@tideh2o.net</a>			
Assigned Technician(s):	John Brown			

## DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and material to replace 40 bulbs and 12 ballasts at MD019.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			3	\$240.00
Centium, Electronic, Fluorescent Ballast	12	\$84.67		\$1,016.04
Linear Fluorescent Bulbs, T5, Miniature Bi-Pin (G5)	40	\$15.02		\$600.80
Labor			8	\$640.00
<b>SUB-TOTAL COSTS:</b>		<b>Materials Total</b>	<b>Labor</b>	<b>\$880.00</b>
		<b>TOTAL</b>		<b>\$2,496.84</b>

All discrepancies, repairs and deficiencies associated with this work order were completed according to the Description of Work Explanation for

## ← Cart

Submit Order

## Purchase Order Number

PO Number (Optional)

## My Products

Reference Information 

ADVANCE



Centium(TM), Electronic, Fluorescent Ballast, Ballast Start Type Programmed

Item # 1FYF7

Qty

12

Total

\$806.40

Your Price \$67.20 / each

 Add Extended Protection Plan for \$20.62 / each.

## Plan Details &amp; Exclusions

## Availability

Expected to arrive Tue. Mar 23.

Remove

GE CURRENT



Linear Fluorescent Bulb, T5, Miniature Bi-Pin (G5), Lumens 2,660 lm, 3,500 K Color Temperature

Item # 5AE19



Qty

40

Total

\$476.80

Your Price \$11.92 / each

## Availability

Expected to arrive Tue. Mar 23.

Remove

## Delivery Method

 Shipping

ITEM: F28T5/835

QTY: 50 PCS

G.W.: - KGS

N.W.: 0.5 KGS

MEAS: 117.5X19X10 CM

MADE IN PRC



