



INVOICE

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

May 4, 2021

RE:Schenectady CSS#29444 NY060
W/O12272 Gate

- Remove gate arm assembly
- Install fiberglass insert in gate arm
- Install gate arm sensing edge
- Connect sensing edge to control module.
- Repair amber light and wiring on gate arm.

(1) Fiberglass insert gate arm assembly 16ft. w/shipping.	2100.00
(1) Sensing edge 23ft.	985.36
(1) aluminum Arm Assembly 26ft	1180.00
8hrs @120.00	960.00

sub total.	5225.36
20% profit/OH.	1045.07

Total.	6270.43

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL