

Additional Funding Request

MD002	CSS# 29633 WO# 13962 Asset# NA							
Description of Repairs	S&S proposes to remove and replace the fan motor & capacitor in cabinet heater #2. S&S will then complete a system check to ensure everything is running properly.							
Diagnosis: Initial Work Order	Repair heating, No2 cabinet heater, fan will not run. Bldg 003.							
Diagnostic Fee	\$ 200 Labor \$100/hr x 1							
Additional Labor Cost to Perform Repairs	\$ 600 Labor \$100/hr x 6							
Additional Material Cost to Perform Repairs	\$ 368.60 <table border="1"><tr><td>Condenser Fan Motor + Shipping</td><td>1</td><td>368.60</td><td>368.60</td></tr></table>				Condenser Fan Motor + Shipping	1	368.60	368.60
Condenser Fan Motor + Shipping	1	368.60	368.60					
Total Cost of Repair	\$ 1168.60							



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 556

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 13962
Quote No: 556
Site: MD002 Ordnance Road
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 03/26/2021
Valid For: 30 Day(s)

WO# 13962

CSS Ticket Number: 29633

Problem: Repair heating, NO2 cabinet heater, fan will not run. Bldg 003.

S&S was onsite and found the capacitor and fan motor in heater 2 were bad.
S&S proposes to remove and replace the fan motor & capacitor in cabinet heater #2.
S&S will then complete a system check to ensure everything is running properly.

Service

Item	Quantity	Unit Price	Total
Condenser Fan Motor/276221	1.00	\$318.60	\$318.60
Shipping	1.00	\$50.00	\$50.00
Diagnosis Fee	1	\$200.00	\$200.00
HVAC Labor Rate	6	\$100.00	\$600.00
Sub-Total ex Tax			\$1,168.60
Tax			\$0.00
Total inc Tax			\$1,168.60

Labor	\$800.00
Materials	\$368.60
Sub-Total ex Tax	\$1,168.60
Tax	\$0.00
Total inc Tax	\$1,168.60



MODEL K46HDXMPZ-1176
VOLT 116

AMP 2.0
HZ 60
THERMALLY PROTECTED AUTO
MFG. NO. K1008
FRAME KEY

PROT. CODE 7AD10
PROT. CODE INFORMATION TO REDUCE

1060

R.P.M. 9F030220
PART NO 9F030220

MADE IN CHINA
INDIVIDUALLY
MADE IN CHINA
www.usmotors.com

WARNING: FOLLOW NATIONAL AND LOCAL CODES FOR
UNUSED LEAD WIRES

GROUNDING AND INSULATE
POWER BEFORE SERVICING
HIDEC MOTOR CORPORATION



JOHNSTONE SUPPLY THE BALSAN GROUP

JOHNSTONE ANNAPOLIS
1981 MORELAND PKWY, SUITE 101
ANNAPOLIS, MD 21401
410-280-0101
Fax 410-280-0104

Quotation

EXPIRATION DATE	QUOTE NUMBER
04/25/2021	100-100981896
JOHNSTONE ANNAPOLIS 1981 MORELAND PKWY, SUITE 101 ANNAPOLIS, MD 21401 410-280-0101 Fax 410-280-0104	PAGE NO. 1 of 1

QUOTE TO:

SHIP TO:

S&S MECHANICAL
4845 SOUTH CRAIN HIGHWAY
UPPER MARLBORO, MD 20772

S&S MECHANICAL
4845 SOUTH CRAIN HIGHWAY
UPPER MARLBORO, MD 20772

CUSTOMER NUMBER	CUSTOMER PO NUMBER	JOB NAME / RELEASE NUMBER	SALESPERSON		
14831	MD002 WO# 13962		HOUSE		
WRITER		SHIP VIA	TERMS	SHIP DATE	FREIGHT ALLOWED
Jimmy Schropp - Anna 43		PICK UP	Net 10th Prox	03/26/2021	No
ORDER QTY	DESCRIPTION			UNIT PRICE	EXT PRICE
1ea	K48HXMPZ-1175 115 VOLTS 60 HZ CONDENSER FAN MOTOR * Non Returnable / Non refundable Pn: 276221			265.500/ea	265.50

Quotation Valid For Days.

Subtotal	265.50
S&H Charges	30.00
Estimated Tax	15.93
Amount Due	311.43