

Additional Funding Request

MD002	CSS# 29642 WO# 14369 Asset# NA							
Description of Repairs	S&S proposes to relocate the emergency stop button to the outside of the room and add a cover.							
Diagnosis: Initial Work Order	Repair emergency stop button for boiler room, bldg 001. Button to be accessible on exterior of boiler room.							
Diagnostic Fee	<p>\$ 200</p> <p>Labor \$100/hr x 2</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 800</p> <p>Labor \$100/hr x 8</p>							
Additional Material Cost to Perform Repairs	<p>\$ 125</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Misc Materials</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 10%; text-align: center;">125</td> <td style="width: 10%; text-align: center;">125</td> </tr> </table>				Misc Materials	1	125	125
Misc Materials	1	125	125					
Total Cost of Repair	\$ 1125.00							



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 632

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 14369
Quote No: 632
Site: MD002 Ordnance Road
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 06/10/2021
Valid For: 30 Day(s)

WO#: 14369

CSS Ticket Number: 14369

Problem: Repair emergency stop button for boiler room bldg 001. Button to be accessible on exterior of boiler room.

S&S proposes to relocate the emergency stop button to the outside of the room and add a cover.

Service

Item	Quantity	Unit Price	Total
Misc Materials	1.00	\$125.00	\$125.00
Diagnosis Fee	1	\$200.00	\$200.00
Electrical Labor Rate	8	\$100.00	\$800.00
Sub-Total ex Tax			\$1,125.00
Tax			\$0.00
Total inc Tax			\$1,125.00

Labor	\$1,000.00
Materials	\$125.00
Sub-Total ex Tax	\$1,125.00
Tax	\$0.00
Total inc Tax	\$1,125.00

