

Additional Funding Request

MD002	CSS# 29647 WO# 15373
Description of Repairs	Tidewater proposes labor to scrape down the damaged area and tape and mud the damaged areas and repaint. The necessary materials are already available onsite.
Diagnosis: Initial Work Order	Repair several settlement cracks in ceiling throughout 1st fl male latrine, bldg. 001. Patch, sand, paint to match.
Diagnostic Fee	\$ 160 Labor \$80/hr x 2
Additional Labor Cost to Perform Repairs	\$ 640 Labor \$80/hr x 8
Additional Material Cost to Perform Repairs	\$ 0
Total Cost of Repair	\$ 800



WORK ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g.,	
E-Mail Address:	adam.colopy@tideh2o.net	Classroom/Room #)	
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor to scrape down the damaged area and tape and mud the damaged areas and repaint. The necessary materials are already available onsite.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Labor			8	\$640.00
SUB-TOTAL COSTS:	Materials Total	\$0.00	Labor	\$800.00
			TOTAL	\$800.00











