

## Additional Funding Request

<b>MD002</b>	<b>CSS# 29912 WO# 13839 Asset# NA</b>				
Description of Repairs	S&S proposes to remove and replace the flue temp sensor. S&S will then complete a system check to ensure the system is running properly.				
Diagnosis: Initial Work Order	# 2 hot water circulating pump VFD faulted out and AHU #1 Exhaust VFD IN alarm also .. possible power issues at site				
Diagnostic Fee	\$ 300  Labor \$300/hr x 1				
Additional Labor Cost to Perform Repairs	\$ 400  Labor \$100/hr x 4				
Additional Material Cost to Perform Repairs	\$ 82.79  <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Parts</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 20%; text-align: center;">82.79</td> <td style="width: 30%; text-align: right;">82.79</td> </tr> </table>	Parts	1	82.79	82.79
Parts	1	82.79	82.79		
Total Cost of Repair	\$ 782.79				



## CUSTOMER QUOTATION NO. 529

Tidewater, Inc.  
Tidewater, Inc  
6625 Selnick Dr.  
Suite A  
Elkridge MD 21075

**Quote Name:** 13839  
**Quote No:** 529  
**Site:** MD002 Ordnance Road  
**Site Contact:**  
**Salesperson:** Lindsay Ruby  
**Created Date:** 03/04/2021  
**Valid For:** 30 Day(s)

**WO#:** 13839

**CSS Ticket Number:** 29112

**Problem:** URGENT # 2 hot water circulating pump VFD faulted out and AHU #1 Exhaust VFD IN alarm also .. possible power issues at site.

S&S hereby proposes to complete the following:

S&S found Boiler #1 had a faulty flue sensor.

S&S will remove and replace the flue temp sensor.

S&S will then complete a system check to ensure the system is running properly.

### Service

Item	Quantity	Unit Price	Total
240962 LOCHINVAR FLUE SENSOR W/GROMMET	1.00	\$68.39	\$68.39
Shipping	1.00	\$14.40	\$14.40
Diagnosis Fee	1	\$300.00	\$300.00
HVAC Labor Rate	4	\$100.00	\$400.00
<b>Sub-Total ex Tax</b>			\$782.79
<b>Tax</b>			\$0.00
<b>Total inc Tax</b>			\$782.79

<b>Labor</b>	\$700.00
<b>Materials</b>	\$82.79
<b>Sub-Total ex Tax</b>	\$782.79
<b>Tax</b>	\$0.00
<b>Total inc Tax</b>	\$782.79



JOHNSTONE ANNAPOLIS  
1981 MORELAND PKWY, SUITE 101  
ANNAPOLIS, MD 21401  
410-280-0101  
Fax 410-280-0104

## Quotation

EXPIRATION DATE	QUOTE NUMBER
05/02/2021	100-100970058
JOHNSTONE ANNAPOLIS 1981 MORELAND PKWY, SUITE 101 ANNAPOLIS, MD 21401 410-280-0101 Fax 410-280-0104	PAGE NO. 1 of 1

QUOTE TO:

S&S MECHANICAL  
4845 SOUTH CRAIN HIGHWAY  
UPPER MARLBORO, MD 20772

SHIP TO:

S&S MECHANICAL  
4845 SOUTH CRAIN HIGHWAY  
UPPER MARLBORO, MD 20772

CUSTOMER NUMBER	CUSTOMER PO NUMBER	JOB NAME / RELEASE NUMBER	SALESPERSON	
14831	MD002 WO# 13839			
WRITER	SHIP VIA	TERMS	SHIP DATE	FREIGHT ALLOWED
Jimmy Schropp - Anna 43	PICK UP	Net 10th Prox	03/03/2021	No
ORDER QTY	DESCRIPTION	UNIT PRICE	EXT PRICE	
1ea	100170642 LOCHINVAR FLUE SENSOR W/ GROMMET * Non Returnable / Non refundable Pn: 240962	56.985/ea	56.99	
<b>Quotation Valid For 20 Days.</b>		Subtotal	56.99	
		S&H Charges	12.00	
		Estimated Tax	3.42	
		Amount Due	72.41	



RESET



SCROLL



LOCKOUT  
FLUE SENSOR FAULT  
SENSOR 1: NONE  
SENSOR 2: 89°F  
SETPOINT

SMART SYSTEM™

Select

Select

