

Additional Funding Request

VA049	CSS# 30364 WO# 14154 05/13/21							
Description of Repairs	Labor and materials to replace the boiler screen display.							
Diagnosis: Initial Work Order	Boiler screen display needs to be replaced.							
Diagnostic Fee	<p>\$ 160</p> <p>Labor \$80/hr x 2</p>							
Additional Labor Cost to Perform Repairs	<p>\$ 160</p> <p>Labor \$80/hr x 2</p>							
Additional Material Cost to Perform Repairs	<p>\$ 658.55</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;">Boiler Screen Display Kit</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 15%; text-align: center;">658.55</td> <td style="width: 15%; text-align: center;">658.55</td> </tr> </table>				Boiler Screen Display Kit	1	658.55	658.55
Boiler Screen Display Kit	1	658.55	658.55					
Total Cost of Repair	\$ 978.55							



WORK ESTIMATE

CSS #:

30364

Work Order #:

14154

Emergency

Urgent

Routine

Company Name:	Tidewater, Inc.		Facility ID:	VA049
Contractor POC:	Adam Cology			
Telephone No:	740-819-6207		Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.cology@tideh2o.net			
Assigned Technician(s):	William Schultz			

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to replace the boiler screen display.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			2	\$160.00
Boiler Screen Repair Kit	1	\$658.55		\$658.55
Labor			2	\$160.00
SUB-TOTAL COSTS:		Materials Total	\$658.55	Labor \$320.00
			TOTAL	\$978.55

15:31:13 MAY 11 2021

Page 1 of 1

FERGUSON ENTERPRISES LLC #1300

Price Quotation

Phone: 804-264-6400
Fax: 804-266-9177

Bid No: B335815
Bid Date: 05/11/21
Quoted By: SYH

Cust Phone: 410-540-8700
Terms: NET 10TH PROX

Customer: TIDEWATER INC
6625 SELNICK DRIVE
FACILITY REPAIRS FOR DIA HQ
SUITE A
ELKRIDGE, MD 21075

Ship To: TIDEWATER INC
6625 SELNICK DRIVE
FACILITY REPAIRS FOR DIA HQ
SUITE A
ELKRIDGE, MD 21075

Cust PO#: BOILER REPAIR KIT

Job Name: FACILITY REPAIRS FOR DIA

Item	Description	Quantity	Net Price	UM	Total
SP-B10621704	DISPLAY REPAIR KIT	1	493.080	EA	493.08
					Net Total: \$493.08
					Tax: \$29.58
					Freight: \$0.00
					Total: \$522.66

Quoted prices are based upon receipt of the total quantity for immediate shipment (48 hours). SHIPMENTS BEYOND 48 HOURS SHALL BE AT THE PRICE IN EFFECT AT TIME OF SHIPMENT UNLESS NOTED OTHERWISE. QUOTES FOR PRODUCTS SHIPPED FOR RESALE ARE NOT FIRM UNLESS NOTED OTHERWISE.

CONTACT YOUR SALES REPRESENTATIVE IMMEDIATELY FOR ASSISTANCE WITH DBE/MBE/WBE/SMALL BUSINESS REQUIREMENTS.

Seller not responsible for delays, lack of product or increase of pricing due to causes beyond our control, and/or based upon Local, State and Federal laws governing type of products that can be sold or put into commerce. This Quote is offered contingent upon the Buyer's acceptance of Seller's terms and conditions, which are incorporated by reference and found either following this document, or on the web at <https://www.ferguson.com/content/website-info/terms-of-sale>
Govt Buyers: All items are open market unless noted otherwise.


LEAD LAW WARNING: It is illegal to install products that are not "lead free" in accordance with US Federal or other applicable law in potable water systems anticipated for human consumption. Products with "NP" in the description are NOT lead free and can only be installed in non-potable applications. Buyer is solely responsible for product selection.



HOW ARE WE DOING? WE WANT YOUR FEEDBACK!

Scan the QR code or use the link below to complete a survey about your bids:

<https://survey.medallia.com/?bidsorder&fc=2020&on=584743>



Panasonic