

Additional Funding Request

VA701	CSS# 30801 WO# 14361 Asset# NA							
Description of Repairs	Provide (8) hours of labor for a controls technician to troubleshoot your Alerton controls system that will not allow you to change setpoints.							
Diagnosis: Initial Work Order	The AHU target air temperature keeps rising and can't make adjustments to building set points							
Diagnostic Fee	\$ 0							
Additional Labor Cost to Perform Repairs	<p>\$ 1680</p> <p>Labor \$130/hr x 8 TWI Labor \$80/hr x 8</p>							
Additional Material Cost to Perform Repairs	<p>\$ 0</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33.33%;">N/A</td> <td style="width: 33.33%;">0</td> <td style="width: 33.33%;">0</td> <td style="width: 33.33%;">0</td> </tr> </table>				N/A	0	0	0
N/A	0	0	0					
Total Cost of Repair	\$ 1680							



Air Conditioning Equipment Sales, Inc.
7314 Impala Drive Richmond, VA 23228
Phone 804-264-2911 Fax 804-264-4785

PROPOSAL

May 26, 20201

Mary Lowry
Project Coordinator
Tidewater, Inc.

RE: VA0701 Service Call

Mary,

Air Conditioning Equipment Sales is pleased to present this proposal for your consideration to provide (8) hours of labor for a controls technician to troubleshoot your Alerton controls system that will not allow you to change setpoints.

This quote includes:

(8) Hours of Technician Labor	\$130.00 / HR	\$1,040.00
-------------------------------	---------------	------------

This quote does not include:

- Any parts, labor, or material not specifically listed in this proposal
- If additional repair labor is found to be needed, that cost will be provided in a separate proposal
- If additional repair parts are needed, that will be provided in a separate proposal

The total cost of this service is not to exceed \$1,040.00. Please confirm the approval of this proposal.

Please let me know if you have any questions.

Respectfully Submitted,

Alley Slaven
Service Coordinator
804.264.2911 X 237
AlleyS@aceshvac.com