

**Additional Funding Request**  
**INVOICE**

<b>VA048</b>	<b>CSS# 30972 WO# 14378 Asset# NA</b>							
Description of Repairs	LoCurrent arrived on site, freed up stuck Gate and adjusted Guide Track so that binding would not occur. Adjusted Limit Switch Blocks and Gate Stop Bolts. Gate is opening and closing properly but recommend additional measures be taken to ensure continuous proper operation.							
Diagnosis: Initial Work Order	Main Gate Stuck open will not move or roll-Urgent with high Priority >Please contact LoCurrent to get serviced or repaired Monday .							
Diagnostic Fee	\$ 0							
Additional Labor Cost to Perform Repairs	<p>\$ 800</p> <p>2 men @ \$75/hr x 5</p> <p>Admin \$50</p>							
Additional Cost	<p>\$ 0</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">N/A</td> <td style="width: 25%;">1</td> <td style="width: 25%;"></td> <td style="width: 25%;"></td> </tr> </table>				N/A	1		
N/A	1							
Total Cost of Repair	\$ 800							

**LoCurrent Systems, LLC**

3522 County Highway 11  
Cooperstown, NY 13326  
(607)293-7300  
locurrent@gmail.com



# INVOICE

**BILL TO**

Tidewater Inc.  
6625- A Selnick Drive  
Elkridge, MD 21075

**INVOICE #** 1942  
**DATE** 06/07/2021  
**DUE DATE** 07/07/2021  
**TERMS** Net 30

**P.O. NUMBER**

Monteith VA048 Main Gate Repair

ACTIVITY	QTY	RATE	AMOUNT
<b>Installation</b>	1	800.00	800.00
Monteith VA048			
Main Gate Repair and Adjustments			
CSS#30972 WO#14378			

Dear Mary:

As per our Site Visit, LoCurrent arrived on site, freed up stuck Gate and adjusted Guide Track so that binding would not occur. Adjusted Limit Switch Blocks and Gate Stop Bolts. Gate is opening and closing properly but recommend additional measures be taken to ensure continuous proper operation.

(2) men 5 hrs @ \$75.....\$750.00  
Administrative.....\$50.00

The cost for the above mentioned work is \$800.00.

Thank you for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

If you have any questions regarding this invoice, please contact Antonietta LoRusso at (607)293-7300.

BALANCE DUE

**\$800.00**

## CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: Montieth VAD48 Date of Visit: 10/5/2021

Contractor Personnel on Site:

1. Nicholas LoRusso 4. \_\_\_\_\_
2. Chris DeNile 5. \_\_\_\_\_
3. \_\_\_\_\_ 6. \_\_\_\_\_

### Service Call Number

CSS# 30972 WO# 14378

### Description of Repairs

Freed up stuck gate & adjusted glide track so that binding would not occur. Adjusted limit switch blocks and gate stop bolts. Recommened the following: Fireplace (1) Gate Roller Bracket, (1) piece extreme drive track, Ant bait to control infestation, (1) Photoeye flood, hydraulic motor service and Cleaning; Change hydraulic fluid, clean gate operator etc.

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Nicholas LoRusso Date: 10/5/2021

Signed: Nicholas LoRusso

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: \_\_\_\_\_ Date: \_\_\_\_\_

Signed: NO one available at the time

E-Mail: OF departure







U.S.  
PROPERTY  
NO  
THEIRS

