

Additional Funding Request

MD002	CSS# 30987 WO# 14387 Asset# NA							
Description of Repairs	S&S proposes to remove and replace two discharge temp sensors in Building 2 AC unit, then complete a system check to ensure everything is now running correctly.							
Diagnosis: Initial Work Order	AC Failure, BLDG 2, Thermostat showing error code P1, manual reset didn't clear them							
Diagnostic Fee	\$ 400 Labor \$100/hr x 4							
Additional Labor Cost to Perform Repairs	\$ 800 Labor \$100/hr x 8							
Additional Material Cost to Perform Repairs	\$ 182.52 <table border="1"><tr><td>Materials</td><td>1</td><td>182.52</td><td>182.52</td></tr></table>				Materials	1	182.52	182.52
Materials	1	182.52	182.52					
Total Cost of Repair	\$ 1382.52							



S&S MECHANICAL

S&S Mechanical
4831 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 644

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 14387
Quote No: 644
Site: MD002 Ordnance Road
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 06/16/2021
Valid For: 30 Day(s)

WO#: 14387

CSS Ticket Number: 30987

Problem: AC Failure, BLDG 2, thermostat showing error code P1, manual reset didn't clear them.

S&S herby proposes to complete the following:

S&S will remove and replace two discharge temp sensors in Building 2 AC unit.

S&S will then complete a system check to ensure everything is now running correctly.

Service

Item	Quantity	Unit Price	Total
CV6233097749 THERMISTOR ASSY	1.00	\$76.26	\$76.26
CV6233097732 THERMISTOR ASSY	1.00	\$76.26	\$76.26
Shipping	1.00	\$30.00	\$30.00
Diagnosis Fee	1	\$400.00	\$400.00
HVAC Labor Rate	8	\$100.00	\$800.00
Sub-Total ex Tax			\$1,382.52
Tax			\$0.00
Total inc Tax			\$1,382.52

Labor	\$1,200.00
Materials	\$182.52
Sub-Total ex Tax	\$1,382.52
Tax	\$0.00
Total inc Tax	\$1,382.52



JOHNSTONE ANNAPOLIS
1981 MORELAND PKWY, SUITE 101
ANNAPOLIS, MD 21401
410-280-0101
Fax 410-280-0104

Quotation

EXPIRATION DATE	QUOTE NUMBER
06/21/2021	100-101030851
JOHNSTONE ANNAPOLIS 1981 MORELAND PKWY, SUITE 101 ANNAPOLIS, MD 21401 410-280-0101 Fax 410-280-0104	PAGE NO. 1 of 1

QUOTE TO:

SHIP TO:

S&S MECHANICAL
4845 SOUTH CRAIN HIGHWAY
UPPER MARLBORO, MD 20772

S&S MECHANICAL
4845 SOUTH CRAIN HIGHWAY
UPPER MARLBORO, MD 20772

CUSTOMER NUMBER	CUSTOMER PO NUMBER	JOB NAME / RELEASE NUMBER	SALESPERSON		
14831	MD002 WO# 14387		HOUSE		
WRITER		SHIP VIA	TERMS	SHIP DATE	FREIGHT ALLOWED
Jimmy Schropp - Anna 43		PICK UP	Net 10th Prox	06/14/2021	No
ORDER QTY	DESCRIPTION			UNIT PRICE	EXT PRICE
1ea	CV6233097749 THERMISTOR ASSY (DISCH1) * Non Returnable / Non refundable Pn: 280196			63.550/ea	63.55
1ea	CV6233097732 THERMISTOR ASSY (DISCH2) * Non Returnable / Non refundable Pn: 280197			63.550/ea	63.55
Quotation Valid For 7 Days. Bid Valid for 7 Days - *Excluding Commodities* 24hrs				Subtotal	127.10
				S&H Charges	0.00
				Estimated Tax	7.63
				Amount Due	134.73

Panasonic

OUTDOOR UNIT
Model No.

U-96MF1U9

Multi Type Air Conditioner
Panasonic Corporation
Osaka, Japan

Made in Japan



25/5/85
U9

SOURCE 230/208V 60Hz 3Ph

SER No. 202-464

85421380636001

		COOL	HEAT
OUTDOOR UNIT TOTAL	AMPS	28.4/30.1	28.4/31.9
COMPRESSOR	AMPS	27.0/28.8	26.9/30.3
OUTDOOR FAN MOTOR	AMPS	1.4/1.5	1.5/1.6
		COMP1	COMP2
RATED LOAD	AMPS	14.3	14.3
LOCKED ROTOR	AMPS	25.0	132.1

MINIMUM CIRCUIT AMPLACITY 34 A

MAXIMUM OVERCURRENT PROTECTION 45 A
(ONE OR TWO TYPE CIRCUIT BREAKER)

REFRIGERANT R410A FACTORY CHARGED 25.9 lbs

DESIGN PRESSURE HIGH SIDE 445 psi

LOW SIDE 238 psi